



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SME 3179T

| Qty                                | Description of Parts  | Condition   | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|---|-------------|---------------------------|-------------------|
| <b><u>REPLACEMENT OF PARTS</u></b> |   |             |                           |                   |
| 1                                  | FRONT FENDER RH (WCP)   | DENTED      | 140.00                    | 140.00            |
| 1                                  | FRONT FENDER SHIELD RH (WCP)  | BENT        | 65.00                     | 65.00             |
| 1                                  | FRONT FENDER 1/4 GLASS MOULDING RH (WCP)  | NECESSARY   | 30.00                     | 30.00             |
| 1                                  | FRONT FENDER 1/4 GLASS RH (WCP)   | CRACKED     | 150.00                    | 150.00            |
| 1                                  | FRONT DOOR RH (WCP)   | DENTED      | 380.00                    | 380.00            |
| 1                                  | FRONT DOOR HINGE TOP RH (WCP)   | SERVICEABLE | 28.00                     | -                 |
| 1                                  | FRONT DOOR HINGE LOWER RH (WCP)   | SERVICEABLE | 28.00                     | -                 |
| 1                                  | FRONT DOOR CHECKER RH (WCP)   | SERVICEABLE | 35.00                     | -                 |
| 1                                  | FRONT DOOR FAME STICKER RH (WCP)  | NECESSARY   | 28.00                     | 28.00             |
| 1                                  | FRONT SIDE MIRROR RH (WCP)  | CRACKED     | 210.00                    | 210.00            |
| 1                                  | FRONT SIDE MIRROR COVER RH (WCP)  | CRACKED     | 20.00                     | 20.00             |
| 1                                  | FRONT FENDER HYBRID EMBLEM (WCP) (ADDITIONAL)                                     | NECESSARY   | 40.00                     | 40.00             |
| 10                                 | FRONT FENDER SHIELD CLIP @\$2.00 (WCP)  | NECESSARY   | 20.00                     | 20.00             |
|                                    | COST PLUS 10%   |             | 117.40                    | 108.30            |
|                                    |   |             | 1,291.40                  | 1,191.30          |
| <b><u>LABOUR</u></b>               |   |             |                           |                   |
|                                    | TO CHECK WIRING SYSTEM.   |             | 30.00                     | 20.00             |
|                                    | TO TRANSFER DOOR MECHANISM TO NEW DOOR.   |             | 40.00                     | 30.00             |
|                                    | TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS. |             | 520.00                    | 400.00            |
|                                    | SPRAY PAINTING CHARGES.   |             | 620.00                    | 500.00            |
|                                    |   |             | 1,210.00                  | 950.00            |
| <b>GRAND TOTAL</b>                 |   |             | <b>2,501.40</b>           | <b>2,141.30</b>   |

|                                    |  |  |                 |
|------------------------------------|--|--|-----------------|
| <b>RECOMMENDED COST OF REPAIRS</b> |  |  | <b>2,141.30</b> |
| <b>LESS EXCESS</b>                 |  |  | <b>-600.00</b>  |
| <b>NETT LIABILITY</b>              |  |  | <b>1,541.30</b> |

Report Ref No. CS/AIS22000647/Vvf3e2

THEVAN THOMAS KARTHIKESAVAN

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.