



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897			Ref: CS/AIS22000647/Vvf3e2	
			Date: 04/03/2022	
			Code: AIS	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	SME 3179T
	Policy No.	SP2000515290-01	Coverage (\$)	0.00
	Claim No.	2022 22003763/SL	Excess (\$)	600.00
	Assign From	SHANTI	Assign Date	18/01/2022
2. Vehicle Particulars & Condition				
	Make & Model	HONDA FIT HYBRID	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	GP51327753	Colour	SILVER
	Odometer	51672 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/55 R15	DUNLOP	6 mm
	L/H Front Tyre	195/55 R15	DUNLOP	6 mm
	R/H Rear Tyre	195/55 R15	DUNLOP	6 mm
	L/H Rear Tyre	195/55 R15	DUNLOP	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	16/01/2022	Inspection Date	18/01/2022
	Survey held at	KAN FOOK SING MOTOR WORKSHOP 61 DEFU LANE 12 SINGAPORE 539147		
5a. Remarks				
	A)THE MARKET VALUE IS S\$57,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	