

RELIABLE CARZ PTE LTD

8 Kaki Bukit Avenue 4 #05-50 Premier @ Kaki Bukit Singapore 415875

Contact No.: +65 8166 9797

Fax No.: +65 6385 1751

Email: reliablecarzpl@gmail.com

not Authorized
Lien
nervous
18/1/12
1/5 \$3900
5 days

Vehicle No.: SLZ3841R

Model: HONDA VEZEL

REF: RC3327

QTY DESCRIPTION

AMOUNT (S\$)

List Items:

1	Trunklid	953	Sodly ID	1287.60	
1	Trunklid Lock		11	269.50	X
2	Trunklid Hinge @ S\$129		11	258.00	X
1	Trunklid Emblem "LOGO"		11	40.30	X
1	Trunklid Emblem "HYBRID"		11	63.00	
1	Trunklid Emblem "VEZEL"		11	56.20	
1	Trunklid Inner Board		11	225.00	X
1	Trunklid Lamp RH	205.10	one	285.00	
1	Trunklid Weatherstrip		811	227.00	X
1	Trunklid Outer Garnish		11	267.80	X
1	Tail Lamp RH	482.00	one	680.00	
1	Rear Bumper	762.00	ID	950.60	
2	Rear Bumper Retainer @ S\$50.90		11	101.80	X
1	Rear Bumper Side RH	180.40	2e	225.30	
1	Rear Bumper Reflector RH		one	151.90	
1	Rear Wheel Arch Garnish RH	182.30	DIS	187.20	
1	Rear End Panel	517.00	ID	585.00	
1	Rear End Panel Top Garnish		11	145.50	X
1	Rear Windscreen Moulding	110.80	111	121.80	
				6128.50	
Less 20 %				(1225.70)	
Subtotal				4902.80	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

RELIABLE CARZ PTE LTD

8 Kaki Bukit Avenue 4 #05-50 Premier @ Kaki Bukit Singapore 415875

Contact No.: +65 8166 9797

Fax No.: +65 6385 1751

Email: reliablecarzpl@gmail.com

not Authorized
18/1/22
4/5 \$
5 days

Vehicle No.: SLZ3841R

Model: HONDA VEZEL

REF: RC3327

QTY DESCRIPTION

AMOUNT (\$\$)

Special Nett Items:

- 1 Rear Windscreen Sealant
- 1 Rear Bumper Clip (Set)
- 1 Rear Reverse Sensor
- 1 Rear Number Plate And Base

net 100.00 40 s/w
net 60.00 40 s/w
shotel 350.00 200 s/w
in 50.00 X

Subtotal 560.00

Labour Charges:

- To Remove & Refix Reverse Sensor System
- To Transfer Tailgate Mechanism
- To Remove & Refix Rear Windscreen Glass
- To Remove & Refix Rear View Camera
- To Check Wiring System
- To Apply Under Coating
- To Panel Beating
- To Spray Painting

200.00 50
180.00 60
200.00 120
80.00 X
120.00 20
150.00 60
1000.00 600
1000.00 800

Subtotal 2930.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$\$ 8392.80

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

2-3663-7
202
2-293096
S.N-280
2-1710
492096 3936