

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

**Our File No:** CS/CTI22000653/GVY3E2

**Date:** 08/02/2022

### REFERENCE

Insured/Claimant: LEE PEI QIAN Policy No: DMPCNA00101132102  
Date of Loss: 04/01/2022 Nature of Claim: OD Claim No: SNM22D200112/C01/THAMYL

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMA6329D**  
Make & Model: TOYOTA VIOS, 1.5 G (A) Engine No: 2NR5233388  
Reg. Date: 14/06/2018 (Man. Year: 2018) Chassis No: MR2B23F3101130197  
Colour: Silver Odometer: 20486 km  
Engine Capacity: 1496 cc  
Market Value/New Car Price: S\$66,800.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/50 R16 Rear Tyre Size: 195/50 R16  
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm  
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	35,624.00	18,697.00	16,927.00	47.52
Miscellaneous Items	300.00	290.00	10.00	3.33
Labour	4,228.80	4,228.80	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>40,152.80</b>	<b>23,215.80</b>	<b>16,937.00</b>	<b>42.18</b>
<b>+ GST 7.00/0.00% (S\$)</b>	<b>2,810.70</b>	<b>0.00</b>	<b>2,810.70</b>	<b>100.00</b>
<b>Nett Amount (S\$)</b>	<b>42,963.50</b>	<b>23,215.80</b>	<b>19,747.70</b>	<b>45.96</b>

### INSPECTION

Date of Assignment: 18/01/2022 Present Location: Car City Auto Centre Pte Ltd (HQ)  
Date Inspected: 19/01/2022 Inspected At: Car City Auto Centre Pte Ltd (HQ)  
Estimated Period of Repair: 0.0 days Blk 9006 #01-198, Tampines Street 93  
Singapore 528840

**Adjuster:** XING GUO QIANG

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(EXCLUDE CHECK ITEMS S\$14,292.00 NETT)

**TOTAL LOSS ASPECT**

Market Value :	\$66,800.00
OMV :	\$15,201.00
PARF Rebate (1) :	\$11,400.00
Quota Premium Paid :	\$38,510.00
COE Rebate (2) :	\$24,652.00
Total Rebate (1) + (2) = :	\$36,052.00

The total amount incurred will be Market Value \$66,800.00 minus Total Rebate \$36,052.00 = \$30,748.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

# REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Feb 2022)
Parts:	143	TOYOTA VIOS 1.5 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMA6329D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PARTS		35,624.00 F	*18,697.00 F
F=Franchise part.						
Total Parts (S\$)					35,624.00	18,697.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	EXTRAS	300.00	290.00
Sub Total (\$\$)			300.00	290.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR	New	3,166.80	3,166.80
2	SPRAY PAINTING	New	1,062.00	1,062.00
Gross Labour Cost (\$\$)			4,228.80	4,228.80

Report was unsubmitted during this print-out.

< END OF ESTIMATES >