

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT SOMPO INSURANCE SINGAPORE PL CS3/SMO22000655/Aqf3e2 Ref: 50 RAFFLES PLACE #03-03 SINGAPORE LAND Date: 24/03/2022 **TOWER SINGAPORE 048623** Code: SMO 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. **SNB 1749R** SMG 7187H Veh. Inspected Policy No. D21MTPV01010544 Coverage (\$) 0.00 Claim No. CMTD2200237/GPL Excess (\$) 0.00 18/01/2022 **GRACE TEO Assign Date** Assign From **Vehicle Particulars & Condition** 2. TOYOTA VIOS c.c 1497 Make & Model HIDDEN 2009 Engine No. Year of Reg. MR053HY9305143798 **BLUE** Chassis No. Colour 275970 KM Odometer Steering IN ORDER **IN ORDER** SPORTS RIM **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 185/60 R15 ARIVO 6 mm 185/60 R15 ARIVO L/H Front Tyre 6 mm 185/60 R15 ARIVO R/H Rear Tyre 6 mm **ARIVO** L/H Rear Tyre 185/60 R15 6 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. 5. **General Information** 15/01/2022 Inspect Date / Time 19/01/2022 ( 10:55 AM ) Accident Date TT MOTORSPORT PTE LTD Survey held at 48 TOH GUAN ROAD EAST #01-103 ENTERPRISE HUB SINGAPORE 608586 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$4,300

Report Ref No. CS3/SMO22000655/Aqf3e2

**Estimate Days of Repair** 

Inspected By

5b.

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

**ESTIMATED NORMAL PERIOD FOR REPAIR:** 

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

5 Working Days

REGD Auto Consultant-SAE, Licensed Appraiser

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.