

Qty	Description
-----	-------------

Page 3

ASSESSMENT REPORT FOR VEHICLE NO. SMU 5130 K

SPECIAL NETT ITEMS

2	FRONT HEADLAMP CLIPS L/R - SET	Necessary	40.00	30	40.00
2	FRONT FENDER INNER SHIELD CLIPS L/R - SET	Necessary	60.00	30	60.00
1	FRONT RH TYRE xnn	Cut	180.00		180.00 X
2	FRONT 15" SPORT RIM L/R	Bent	980.00	300	980.00
Special Nett Total :			1,260.00		1,260.00

360

LABOUR

S/N	Description	Workshop's Estimate	Our Assessment
1	To remove, reinstall electrical wiring harness, check lighting.	120.00	60 100.00
2	To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.	450.00	100 400.00
3	To road test driving, check and resetting wheel alignments system.	160.00	60 140.00
4	To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1,400.00	1100 1,200.00
5	To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1,400.00	1,200.00 800
6	To apply anti-rust chemical on repaired and replaced panel.	100.00	40 80.00
Labour Total :		3,630.00	3,120.00
TOTAL (PARTS & LABOUR) \$		11,772.56	7,671.44

The workshop has agreed to undertake the repair cost of the final adjusted Sum contract amount is

\$6,100.00

(SINGAPORE DOLLARS SIX THOUSAND ONE HUNDRED ONLY)



Amas Ong
Automobile Assessor

2275.68

360.00

2160.00

4795.68

20%

3836.54

L/S-\$3,850/8 DAYS