



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS/LPC22000658/Uqf3e2	
			Date: 02/03/2022	
			Code: LPC2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	SLH 7547J
	Policy No.	Z21VP05029887	Coverage (\$)	0.00
	Claim No.	21/22/22/VP05/025383	Excess (\$)	500.00
	Assign From	GERALD POH	Assign Date	18/01/2022
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ GLA180 (A)	c.c	1595
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	WDC1569422J280941	Colour	SILVER
	Odometer	80705 KM	Steering	AFFECTED
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/50 R18	YOKOHAMA	7 mm
	L/H Front Tyre	235/50 R18	YOKOHAMA	7 mm
	R/H Rear Tyre	235/50 R18	PIRELLI	7 mm
	L/H Rear Tyre	235/50 R18	PIRELLI	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	17/01/2022	Inspection Date	19/01/2022
	Survey held at	SME MOTOR PTE LTD 1 KAKI BUKIT AVE 6 #02-15 (AUTOBAY @KAKI BUKIT) SINGAPORE 417883		
5a. Remarks				
	A)THE MARKET VALUE IS S\$84,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	