

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22000659/KPA3Q2**Date:** 16/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070090731
Claimant Vehicle No :	SKT3817E	Insured Vehicle No :	SKH6600G
Date of Loss:	15/01/2022	Nature of Claim:	TP
		Claim No:	7880341021SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKT3817E		
Make & Model:	PEUGEOT 308, 1.2 SW ALLURE PURETECH 2WD S/R. (A)	Engine No:	10XT180049932
Reg. Date:	03/06/2015 (Man. Year: 2015)	Chassis No:	VF3LRHNYWFS033381
Colour:	Metallic White	Odometer:	76733 km
Engine Capacity:	1199 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 7 mm	Rear Left Side:	Pirelli 7 mm
Front Right Side:	Pirelli 7 mm	Rear Right Side:	Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,867.00	4,855.70	2,011.30	29.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,350.00	1,430.00	920.00	39.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,217.00	6,285.70	2,931.30	31.80
Approved Total (Overridden) (S\$)		5,000.00		
(S\$)	9,217.00	5,000.00	4,217.00	45.75
+ GST 7.00/7.00% (S\$)	645.19	350.00	295.19	45.75
Nett Amount (S\$)	9,862.19	5,350.00	4,512.19	45.75
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		31.00		
Nett Liability (S\$)		5,681.00		
Global Sum Settlement (S\$)		5,680.00		

INSPECTION

Date of Assignment:	18/01/2022		
Date Inspected:	18/01/2022	Inspected At:	Optima Werkz Pte Ltd (HQ) 6 Kung Chong Road Singapore 159143
Estimated Period of Repair:	4.0 days		

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP LH	Cut	660.00 FL	*660.00 FL
2	1		*FRONT BUMPER	Buckled	1,000.00 FL	*841.00 FL
3	1		*FRONT BUMPER SIDE RETAINER LH	Distorted	100.00 FL	*100.00 FL
4	1		*FRONT BUMPER OUTER CHROME MOULDING LH	Cut	250.00 FL	*250.00 FL
5	1		*FRONT BUMPER DAY LIGHT LED LH	Mtg Cracked	240.00 FL	*168.00 FL
6	1		*FRONT FENDER LH	Bent	530.00 FL	*530.00 FL
7	1		*FRONT FENDER INNER SHIELD LH	Cracked	220.00 FL	*220.00 FL
8	1		*FRONT SPORT RIM LH	Dented	1,360.00 FL	*1,284.00 FL
9	1		*FRONT SUSPENSION SHOCK ABSORBER LH	Bent	580.00 FL	*490.00 FL
10	1		*FRONT SUSPENSION KNUCKLE ARM WITH BEARING LH	Bent	500.00 FL	*500.00 FL
11	1		*FRONT SUSPENSION LOWER ARM LH	Distorted	230.00 FL	*230.00 FL
12	1		*FRONT BONNET	Repair	1,560.00 FL	*- FL
13	1		*FRONT HEADLAMP CLIPS LH	Necessary	20.00 FS	*20.00 FS
14	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
15	1		*FRONT FENDER INNER SHIELD CLIPS LH	Necessary	40.00 FS	*40.00 FS
16	1		*FRONT TYRE LH -205/55R16	Serviceable	250.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	7,590.00	5,383.00
- List Item Discount on L Items 10.00/10.00% (S\$)	723.00	527.30
Total Parts (S\$)	6,867.00	4,855.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REPAIR REFIX & READJUST FRONT ACCIDENT AREAS & ETC	New	800.00	550.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT ACCIDENT AREAS & ETC	New	1,000.00	660.00
3	TO TUFF KOTE & UNDERSEAL MATERIALS	New	120.00	30.00
4	TO WHEEL ALIGNMENT & BALANCING	New	100.00	20.00
5	TO DAIGNOSIS FAULT CODE & RESET MEMORY	New	100.00	0.00
6	TO REMOVE & REFIX FRONT WHEEL SUPPENSION ARM & ETC TO EFFECT ON FRONT FENDER RH	New	150.00	150.00
7	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC	New	80.00	20.00
Gross Labour Cost (\$\$)			2,350.00	1,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >