

OPTIMA WERKZ

SINGAPORE

OPTIMA WERKZ PTE LTD
Co. Reg. No. 201212455W
www.ow.sg

OptimaWerkz

Date: 18/01/2022
Vehicle No: SKT3817E
Model: PEUGEOT 308 SW 1.2
Chassis: VF3LRHNYWFS033381
Reg. Year: 2015

Third Party Insurer: AIG
Third Party Veh No: SKH6600G
Date of Accident: 15/01/2022
Estimator: KIT
Surveyor:

Not Notified
11 Pay @ 5000/-
Penny After Paid
4-5 days

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT HEADLAMP LH	1		WT \$660.00
2	FRONT BUMPER 841	1		Bu \$1,000.00
3	FRONT BUMPER SIDE RETAINER LH	1		D.I \$100.00
4	FRONT BUMPER OUTER CHROME MOULDING LH	1		WT \$250.00
5	FRONT BUMPER DAY LIGHT LED LH 188	1		mgc \$240.00
6	FRONT FENDER LH	1		Ry \$530.00
7	FRONT FENDER INNER SHIELD LH	1		CM \$220.00
8	FRONT SPORT RIM LH 1284	1		WT \$1,360.00
9	FRONT SUSPENSION SHOCK ABSORBER LH 490	1		Ry \$580.00
10	FRONT SUSPENSION KNUCKLE ARM WITH BEARING LH	1		Ry \$500.00
11	FRONT SUSPENSION LOWER ARM LH	1		D.I \$230.00
12	FRONT BONNET	1		R \$1,560.00
SUB TOTAL				\$7,230.00
LESS 10%				\$723.00
PARTS TOTAL				\$6,507.00

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT HEADLAMP CLIPS LH	1		WT \$20.00
2	FRONT BUMPER CLIPS	1		WT \$50.00
3	FRONT FENDER INNER SHIELD CLIPS LH	1		WT \$40.00
4	FRONT TYRE LH - 205/55R16	1		WT \$250.00
S/N TOTAL				\$360.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

OW

Date: 18/01/2022
Vehicle No: SKT3817E
Model: PEUGEOT 308 SW 1.2
Chassis: VF3LRHNYWFS033381
Reg. Year: 2015

Third Party Insurer: AIG
Third Party Veh No: SKH6600G
Date of Accident: 15/01/2022
Estimator: KIT
Surveyor:

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR, REFIX & READJUST FRONT ACCIDENT AREAS & ETC.	\$800.00	5501
LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT ACCIDENT AREAS & ETC.	\$1,000.00	6601
TO TUFF KOTE & UNDERSEAL MATERIALS.	\$120.00	301
TO WHEEL ALIGNMENT & BALANCING	\$100.00	201
TO DAIGNOSIS FAULT CODE & RESET MEMORY.	\$100.00	X
TO REMOVE & REFIX FRONT WHEEL SUPPENSION ARM & ETC. TO EFFECT ON FRONT FENDER RH	\$150.00	2
TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.	\$80.00	201

LABOUR TOTAL \$2,350.00

TOTAL \$9,217.00

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9910 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

