

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: JTES013

at Workshop m/s: Enofc
of: SHS 4488R

Inured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: RM9000

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: JTES013 Yr Regn: 22/02/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yanche Y157R c.c 150

Colour: Blue A/C: Insured / Std / NI / NA

Sp.Reading: 61887 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: PMYU4051 OK0225469

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 70-90-17

R: 80-90-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: 6 mm Rear: 6 mm


R/Bal. 6 mm L/Bal. 6 mm

D.O.A. 8/1/22 D.O.I. 18/1/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

n/s Rear & o/s body. The U/C / Chassis frame / Body Structure affected due to collision.



26/2/22 4/5 @ 1800 informed MR Teo

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

Add Fee: : Site Insp (\$) : Interview (\$) : Tech. Invs (\$) : Weekend (\$)

Report Format :

Lump Sum / I.B.I: (\$)

TOTAL

Large empty rectangular box for additional notes or calculations.

AX17

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Name : Vasudevan A/L Nadarajah

*not Approved
den*

Accident Date : 08-Jan-22

Vehicle No : JTE5013

*18/1/22 a/s #1800
take up. Att. up
4 days*

Vehicle Model : Yamaha Y15ZR

Estimated Repair Costs

| Qty | Description | Amount S(\$) |
|-----|--|--------------------|
| | <u>List Items</u> | |
| 2 | Front fork tube assy <i>SU</i> | \$ 640.00 <i>X</i> |
| 1 | Fork under bracket <i>u 1</i> | \$ 185.00 <i>X</i> |
| 1 | Front wheel rim <i>u 1</i> | \$ 280.00 <i>X</i> |
| 1 | Front rim shaft <i>u 1</i> | \$ 45.00 <i>X</i> |
| 1 | Front rim bearing <i>u 1</i> | \$ 38.00 <i>X</i> |
| 1 | Front brake disc <i>u 1</i> | \$ 155.00 <i>X</i> |
| 1 | Mirror <i>o/s</i> <i>cu 1</i> | \$ 60 80.00 ✓ |
| 1 | Handle-bar <i>Surf</i> | \$ 88.00 ✓ |
| 1 | Handle-bar end (1 set) <i>m.s/cu 1</i> | \$ 30 65.00 ✓ |
| 1 | Hand grip (1 set) <i>Twin</i> | \$ 55.00 ✓ |
| 1 | Front horn inner cover centre matt black <i>cu 1</i> | \$ 70.00 ✓ |
| 1 | Front signals <i>o/s</i> <i>cu 1</i> | \$ 75 140.00 ✓ |
| 1 | Pilot lights <i>one</i> | \$ 155 228.00 ✓ |
| 1 | Brake lever <i>Surf</i> | \$ 55.00 ✓ |
| 1 | Fairing assy (1 set) <i>cu 1</i> | \$ 525.00 ✓ |
| 1 | Front footrest <i>Surf</i> <i>cu 1</i> | \$ 48 95.00 ✓ |
| 1 | Front footrest bracket (1 set) <i>Surf</i> | \$ 70.00 ✓ |
| 1 | Brake pedal <i>Surf</i> | \$ 42.00 ✓ |
| 1 | Master pump <i>cu 1</i> | \$ 230.00 ✓ |
| 1 | Rear footrest (1 set) <i>u 1</i> | \$ 80.00 ✓ |
| 1 | Rear footrest bracket <i>u 1</i> | \$ 78.00 <i>X</i> |
| 1 | Exhaust assy <i>RD</i> | \$ 485.00 ✓ |
| 1 | Exhaust protector - rear <i>Twin</i> | \$ 60.00 ✓ |
| 1 | Exhaust protector - front <i>Twin</i> | \$ 45.00 ✓ |
| 1 | Exhaust pipe end cover <i>Twin</i> | \$ 55.00 ✓ |
| 1 | Rear handle <i>u</i> | \$ 180.00 <i>X</i> |
| 1 | Rear signals (1 set) <i>Misc</i> | \$ 75 140.00 ✓ |
| | | \$ 4,209.00 |
| | Less 10% | \$ 420.90 |
| | | \$ 3,788.10 |

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Name : Vasudevan A/L Nadarajah

Accident Date : 08-Jan-22

Vehicle No : JTE5013

Vehicle Model : Yamaha Y15ZR

Estimated Repair Costs

Special Net Items

| | | | | |
|---|---------------------------------------|----|---------------|-----------|
| 1 | Number plate (1 set) <i>Rear Seat</i> | \$ | 38.00 | <i>10</i> |
| 2 | Fork oils <i>17</i> | \$ | 30.00 | <i>X</i> |
| 2 | Fork oil seals <i>17</i> | \$ | 56.00 | <i>X</i> |
| 1 | Steering cone (1 set) <i>17</i> | \$ | 95.00 | <i>X</i> |
| 1 | Sticker (1 set) <i>17</i> | \$ | 120.00 | <i>60</i> |
| | | \$ | <u>339.00</u> | |


S/No. Labour

| | | | | |
|---|---|----|------------------|------------|
| 1 | To provide towing service (LOD) | \$ | 30.00 | <i>✓</i> |
| 2 | To check wiring and reset headlamp focusing | \$ | <i>17</i> 80.00 | <i>X</i> |
| 3 | To repair body frame | \$ | <i>17</i> 350.00 | <i>X</i> |
| 4 | To provide labour | \$ | 480.00 | <i>220</i> |
| | | \$ | <u>940.00</u> | |

Grand Total

\$ 5,067.10

Singapore Dollars: Five Thousand Sixty-Seven and Cents: Ten only


EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

p-2223
102
2000.7
2300.7
1800.