

AXIA

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Name : Vasudevan A/L Nadarajah

not Andrew Lee

Accident Date : 08-Jan-22

Vehicle No : JTE5013

18/1/22

o/s

Vehicle Model : Yamaha Y15ZR

recept. Atk upon

4 days

Estimated Repair Costs

Qty	Description	Amount S(\$)
List Items		
2	Front fork tube assy <i>Sub</i>	\$ 640.00 <i>X</i>
1	Fork under bracket <i>u1</i>	\$ 185.00 <i>X</i>
1	Front wheel rim <i>u1</i>	\$ 280.00 <i>X</i>
1	Front rim shaft <i>u1</i>	\$ 45.00 <i>X</i>
1	Front rim bearing <i>u1</i>	\$ 38.00 <i>X</i>
1	Front brake disc <i>u1</i>	\$ 155.00 <i>X</i>
1	Mirror <i>o/s</i> <i>cut</i>	\$ 80.00 <i>✓</i>
1	Handle-bar	\$ 88.00 <i>?</i>
1	Handle-bar end (1 set) <i>m.s/cut</i>	\$ 65.00 <i>—</i>
1	Hand grip (1 set) <i>u1</i>	\$ 55.00 <i>—</i>
1	Front horn inner cover centre matt black <i>cut</i>	\$ 70.00 <i>—</i>
1	Front signals <i>o/s</i> <i>cut</i>	\$ 140.00 <i>—</i>
1	Pilot lights <i>one</i>	\$ 228.00 <i>—</i>
1	Brake lever <i>best</i>	\$ 55.00 <i>—</i>
1	Fairing assy (1 set) <i>cut</i>	\$ 525.00 <i>—</i>
1	Front footrest <i>best cut</i>	\$ 95.00 <i>—</i>
1	Front footrest bracket (1 set) <i>best</i>	\$ 70.00 <i>—</i>
1	Brake pedal <i>best</i>	\$ 42.00 <i>—</i>
1	Master pump <i>cut</i>	\$ 230.00 <i>—</i>
1	Rear footrest (1 set) <i>u1</i>	\$ 80.00 <i>✓</i>
1	Rear footrest bracket <i>u1</i>	\$ 78.00 <i>X</i>
1	Exhaust assy <i>PD</i>	\$ 485.00 <i>—</i>
1	Exhaust protector - rear <i>u1</i>	\$ 60.00 <i>—</i>
1	Exhaust protector - front <i>u1</i>	\$ 45.00 <i>—</i>
1	Exhaust pipe end cover <i>u1</i>	\$ 55.00 <i>—</i>
1	Rear handle <i>u</i>	\$ 180.00 <i>X</i>
1	Rear signals (1 set) <i>m/s one</i>	\$ 140.00 <i>—</i>
		\$ 4,209.00
	Less 10%	\$ 420.90
		\$ 3,788.10

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Name : Vasudevan A/L Nadarajah

Accident Date : 08-Jan-22


Vehicle No : JTE5013

Vehicle Model : Yamaha Y15ZR

Estimated Repair Costs

<u>Special Net Items</u>			
1	Number plate (1 set) <i>Rear Seat</i>	\$	38.00 <i>10</i>
2	Fork oils <i>17</i>	\$	30.00 <i>X</i>
2	Fork oil seals <i>17</i>	\$	56.00 <i>X</i>
1	Steering cone (1 set) <i>17</i>	\$	95.00 <i>X</i>
1	Sticker (1 set) <i>17</i>	\$	120.00 <i>60</i>
		\$	<u>339.00</u>
<u>S/No.</u>	<u>Labour</u>		
1	To provide towing service (LOD)	\$	30.00 <i>✓</i>
2	To check wiring and reset headlamp focusing	\$	<i>17</i> 80.00 <i>X</i>
3	To repair body frame	\$	<i>17</i> 350.00 <i>X</i>
4	To provide labour	\$	480.00 <i>220</i>
		\$	<u>940.00</u>
Grand Total		\$	<u>5,067.10</u>

Singapore Dollars: Five Thousand Sixty-Seven and Cents: Ten only


EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: