

SERVICE ESTIMATE

68151 - C00001
 Mr Sw Chan Kit
 2 Sembawang Walk
 #01-85

SL: SERVICE SALES - PC

Singapore 757616

Closed by : Paul Ong Qing Yong
 Svc Consultant : ACC
 Remarks : Mr Sw Chan Kit

GST Reg.No:M28920628X
 Inv.No. . : B&P 0 Page 1
 Inv.date. : 26/03/2022
 WIP No. . : 64618
 Veh.In/Out: 07/03/2022 26/03/2022
 *Tel.No. . : Mobile: 97545918
 Reg.No. . : SLT3776C
 Reg.date . : 26/10/2017
 Mileage .. : 72,627
 Chassis No: SALRA2AK8HA038154

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BUMPER, REAR BOOTLID, BOOTLAMP, BUMPER TOW COVER	0	2600.00	0		2,600.00	S
800	TO SPRAYPAINT ON BOOTLID, REAR FENDER LH ETC	0	2000.00	0		2,000.00	S
802	TO REPLACE REAR WINDSCREEN	0	600.00	0		600.00	S
0080	TO INSTALL REAR WINDSCREEN FIL	0	280.00	0		280.00	S
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	621.00	0		621.00	S
802	TO REMOVE, REFIT & TRANSFER REAR TAILGATE COMPONENTS	0	500.00	0		500.00	S
	BUMPER - REAR	1.0 EA	2171.20	10		1,954.08	S
	COVER - TOWING HOOK	1.0 EA	432.30	10		389.07	S
	LAMP - DAYTIME RUNNI	1.0 EA	1085.80	10		977.22	S
	LAMP - DAYTIME RUNNI	1.0 EA	1085.80	10		977.22	S
	TAILGATE - COMPLETE	1.0 EA	2808.40	10		2,527.56	S

SERVICE ESTIMATE

68151 - C00001
 Mr Sw Chan Kit
 2 Sembawang Walk
 #01-85

SL: SERVICE SALES - PC

Singapore 757616

Closed by : Paul Ong Qing Yong
 Svc Consultant : ACC
 Remarks : Mr Sw Chan Kit

GST Reg.No:M28920628X
 Inv.No. . : B&P 0 Page 2
 Inv.date. : 26/03/2022
 WIP No. . : 64618
 Veh.In/Out: 07/03/2022 26/03/2022
 *Tel.No. . : Mobile: 97545918
 Reg.No. . : SLT3776C
 Reg.date . : 26/10/2017
 Mileage .. : 72,627
 Chassis No: SALRA2AK8HA038154

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	SEAL - TAILGATE	1.0 EA	260.10	10		234.09	S
	GLASS - TAILGATE WIN	1.0 EA	2711.50	10		2,440.35	S
	D PRIMER GLASS & P	1.0 EA	43.30	10		38.97	S
	ADHESIVE AND SEALER	2.0 EA	159.50	10		287.10	S
	NAME PLATE - PLASTIC	1.0 EA	202.20	10		181.98	S
	NAME PLATE - PLASTIC	1.0 EA	185.00	10		166.50	S
	rNAME PLATE	1.0 EA	98.60	10		88.74	S
	NAME PLATE Td6	1.0 EA	159.10	10		143.19	S
	LAMP - FOG - LH REAR	1.0 EA	651.50	10		586.35	S
	BRACKET - BUMPER MOU	1.0 EA	94.90	10		85.41	S
	MOULDING - TAILGATE	1.0 EA	1394.80	10		1,255.32	S
	BLIND - TAILGATE	1.0 EA	816.00	10		734.40	S
	LAMP - FOG - REAR bro	1.0 EA	684.10	10		615.69	S
	REINFORCEMENT - REAR	1.0 EA	680.30	10		612.27	S
	INSERT - BUMPER RH	1.0 EA	147.10	10		132.39	S
	INSERT - BUMPER LH	1.0 EA	146.50	10		131.85	S
	PANEL - TAILGATE TRI	1.0 EA	205.20	10		184.68	S

SERVICE ESTIMATE

68151 - C00001
 Mr Sw Chan Kit
 2 Sembawang Walk
 #01-85

SL: SERVICE SALES - PC

Singapore 757616

Closed by : Paul Ong Qing Yong
 Svc Consultant : ACC
 Remarks : Mr Sw Chan Kit

GST Reg.No:M28920628X
 Inv.No. . : B&P 0 Page 3
 Inv.date. : 26/03/2022
 WIP No. . : 64618
 Veh.In/Out: 07/03/2022 26/03/2022
 *Tel.No. . : Mobile: 97545918
 Reg.No. . : SLT3776C
 Reg.date . : 26/10/2017
 Mileage .. : 72,627
 Chassis No: SALRA2AK8HA038154

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	PANEL - TAILGATE TRI	1.0 EA	205.20	10		184.68	S

			Gross Total.	21,530.11
Labour Total	6,601.00		Net.....	21,530.11
Parts Total	14,929.11		GST @ 7.0%	1,507.11
Package Total	0.00		Total.....	23,037.20
			Paid.....	0.00
			Please Pay..	23,037.20

GST: S=StdRated; O=OutOfScope; Z=ZeroRated