



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: OH VALE			Ref: CS3/ASM22000670/Vqy3e2 Date: 16/03/2022 Code: ASM	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SH 7288Z	Veh. Inspected	SJG 2247L
	Policy No.		Coverage (\$)	0.00
	Claim No.	S2M03RCK	Excess (\$)	0.00
	Assign From	OH VALE	Assign Date	19/01/2022
2. Vehicle Particulars & Condition				
	Make & Model	SUZUKI SX4	c.c	1586
	Engine No.	HIDDEN	Year of Reg.	2008
	Chassis No.	JSAGYA21S00119683	Colour	ORANGE
	Odometer	194994 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/60 R15	BRIDGESTONE	5 mm
	L/H Front Tyre	205/60 R15	BRIDGESTONE	5 mm
	R/H Rear Tyre	205/60 R15	BRIDGESTONE	5 mm
	L/H Rear Tyre	205/60 R15	BRIDGESTONE	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.			
5. General Information				
	Accident Date	15/01/2022	Inspect Date / Time	20/01/2022 (04:30 PM)
	Survey held at	SYNERGY MOTOR 53 UBI AVE 1 #01-45 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	

Report Ref No. CS3/ASM22000670/Vqy3e2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.