

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0036/2022/JT
DATE : 13-Jan-22
WIP : 63354

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 14/1/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

hi Adrian

4 days - ok - Johnny Boo

20-Apr-22

OWNER'S NAME : MR NEO CHOON HONG
ADDRESS : 97 DUCHESS AVENUE
SINGAPORE 269144
TELEPHONE : HP +65 98350341
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900249328-02
VEHICLE NO : **SFV 1331 B**
MODEL CODE : AUDI A4 SEDAN 2.0 TFSI
MODEL YEAR : 21/11/2019
ENGINE NO : CVK 0868411
CHASSIS NO : WAUZZZF41KA109458
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 12-Jan-22
PLACE OF ACCIDENT : CORONATION ROAD

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFV 1331 B

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$ 480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	\$ 250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,100.00	\$ 1,000.00
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER.	\$	2,000.00	\$ 1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$	5,122.00	\$ 3,022.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFV 1331 B

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 1,913.00	\$	1,530.40
2	FRONT BUMPER FIXING PARTS	1	\$ 612.00		
3	FRONT BUMPER SECURING STRIP	2	\$ 79.00		
4	FRONT BUMPER GRILLE - CENTER	1	\$ 219.00		
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	1	\$ 254.00	\$	203.20
6	FRONT BUMPER AIR GUIDE - LH	1	\$ 72.00		
7	RADIATOR GRILLE	1	\$ 1,478.00		
8	FRONT BUMPER AIR GUIDE GRILLE - LH	1	\$ 151.00		
9	FRONT BUMPER GUIDE SECTION - LH	1	\$ 41.00	\$	32.24
10	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 899.00		
11	FRONT BUMPER FOAM FILLER PIECE	1	\$ 139.00		
12	FRONT BUMPER TOP COVER	1	\$ 143.00		
13	CAUTION STICKER	1	\$ 16.00		
14	AIR COND STICKER	1	\$ 9.00		
15	FRONT BUMPER LOCK CARRIER BRACKET	1	\$ 154.00	\$	122.80
16	FRONT BUMPER SUPPORT - LH / RH	2	\$ 64.00		
17	POP RIVET	4	\$ 4.00		
18	FRONT PARKING AID SENSOR -INNER / OUTER	2	\$ 64.00		
19	FRONT PARKING AID SENSOR SEAL RING	4	\$ 10.00		
20	HORN - LH	1	\$ 134.00		
SUB TOTAL SPARE PARTS		:	\$ 6,455.00	\$	1,888.64

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFV 1331 B

					DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS		
		<i>c/f</i>			\$	1,888.64
21	HORN BRACKET - LH	1	\$	33.00		
22	FRONT FENDER - LH	1	\$	861.00	\$	688.80
23	FRONT FENDER ATTACHMENT PARTS	1	\$	211.00		
24	FRONT FENDER CLOSING ELEMENT - LH	1	\$	81.00	\$	64.24
25	FRONT FENDER BRACKET - LH	1	\$	41.00		
26	FRONT FENDER BRACE - LH	1	\$	132.00	\$	105.20
27	POP RIVET	7	\$	27.00	\$	30.40
28	FRONT WHEEL HOUSING LINER - LH	1	\$	260.00		
29	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1		TBC		
30	FRONT WHEEL SPOILER - LH	1	\$	82.00	\$	65.12
31	FRONT WHEEL SPOILER LOWER - LH	1	\$	39.00		
32	HEADLIGHT - LH	1	\$	7,693.00	\$	6,154.40
33	LIFT CYLINDER BRACKET	1	\$	7.00		
34	LIFT CYLINDER - LH	1	\$	231.00		
35	LIFT CYLINDER CORRUGATED PIPE	1	\$	107.00		
36	RADIATOR AIR GUIDE INNER / OUTER - LH	2	\$	46.00		
37	RADIATOR AIR GUIDE UPPER - LH	1	\$	19.00		
38	FRONT NO PLATE	S/N	\$	60.00		
40	SUNDRIES		\$	300.00		20.16
TOTAL SPARE PARTS		:	\$	16,685.00	\$	9,016.96
TOTAL LABOUR CHARGES		:	\$	5,122.00	\$	3,022.00
GRAND TOTAL		:	\$	21,807.00	\$	12,038.96

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

bl-11/03/22

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT