



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2205839

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 20/09/2022
Reference CC6/CTI22000672/Apa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SKX 600L
Insured Veh. CB 148L
Claim No. SNM22D200388/C02
Policy No. DMB1SNW00002632100
Accident Date 14/01/2022
Inspection Date 17/01/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Ref: CC6/CTI22000672/Apa3q2	
			Date: 20/09/2022	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	CB 148L	Veh. Inspected	SKX 600L	
Policy No.	DMB1SNW00002632100	Coverage (\$)	0.00	
Claim No.	SNM22D200388/C02	Excess (\$)	0.00	
Assign From		Assign Date	17/01/2022	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. X5	c.c	2979	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	WBAKR020900K90599	Colour	WHITE	
Odometer	85991 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	255/50 R19	PIRELLI	6 mm	
L/H Front Tyre	255/50 R19	PIRELLI	6 mm	
R/H Rear Tyre	255/50 R19	PIRELLI	6 mm	
L/H Rear Tyre	255/50 R19	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/01/2022	Inspection Date	17/01/2022	
Survey held at	ADVANCE AUTO GARAGE 23 KAKI BUKIT AVENUE 4, #04-01 VICOM KAKI BUKIT INSPECTION CENTER, SINGAPORE 415933.			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKX 600L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	DISTORTED	1,296.00	1,296.00
1	FRONT BUMPER SIDE HOLDER LH	NECESSARY	80.00	80.00
1	FRONT BUMPER SPONGE	CRACKED	125.00	125.00
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	685.00	-
1	FRONT BUMPER FOG LAMP	CRACKED	309.00	309.00
1	FRONT BUMPER SIDE GRILLE LH	CRACKED	142.00	142.00
1	FRONT BUMPER SIDE GRILLE GARNISH LH	NOT NECESSARY	95.00	-
1	FRONT BUMPER LOWER GARNISH	DEFORMED	295.00	295.00
2	FRONT BUMPER SENSOR @\$250.00	DAMAGED (1 PCS ONLY)	500.00	250.00
6	FRONT BUMPER SENSOR HOLDER @\$25.00	NECESSARY	150.00	150.00
1	HEADLAMP LH	CRACKED	2,950.00	2,950.00
1	HEADLAMP ECU	NOT NECESSARY	980.00	-
1	FRONT LH FENDER	TO REPAIR SEE LABOUR	1,008.00	-
1	FRONT LH FENDER ARC GARNISH	CUT	286.00	286.00
1	FRONT LH FENDER INNER SHIELD	TORN	245.00	245.00
1	FRONT LH WHEEL RIM	NOT NECESSARY	1,550.00	-
	LESS 10% DISCOUNT		-	-612.80
			10,696.00	5,515.20
<u>SPECIAL NETT ITEMS</u>				
1	FRONT BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	FRONT LH FENDER INNER SHIELD CLIPS (SN)	NECESSARY	30.00	30.00
1	FRONT LH TYRE (SN)	NOT NECESSARY	300.00	-
			360.00	60.00
<u>LABOUR</u>				
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT LH FENDER .		600.00	300.00
	SPRAY PAINTING.		600.00	400.00
	WIRING.		50.00	30.00
	TO PERFORM WHEEL ALIGNMENT.	NOT NECESSARY	150.00	-

Report Ref No. CC6/CTI22000672/Apa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE FRONT BUMPER SENSOR.		100.00	60.00
	TO PERFORM DIANOGSTIC TEST.		200.00	150.00
			1,700.00	940.00
GRAND TOTAL			12,756.00	6,515.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE -ACCIDENT CONDITION)				5,200.00

Report Ref No. CC6/CTI22000672/Apa3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKX 600L

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKX 600L

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKX 600L

RE-INSPECTION

