

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/1079/2021/JT
DATE : 3-Jan-22
WIP : 60938

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 18/1/22

YOUR INSURED VEH NO : SKU 8811 H

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

4 days - ok - Johnny Boo

8-Apr-22

OWNER'S NAME : MS GU YANYUN
ADDRESS : BLK 71 MARINE DRIVE
#05-232
SINGAPORE 440071
TELEPHONE : HP +65 96736545
TYPE OF CLAIM : OWDN DAMAGED CLAIM
POLICY NO : 7210027649
VEHICLE NO : **SGE 6176 C**
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI
MODEL YEAR : 22/3/2021
ENGINE NO : CHZ C34154
CHASSIS NO : WAUZZZ8V5LA000654
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 28-Dec-21
PLACE OF ACCIDENT : 8A PATERSON HILL

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SGE 6176 C

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER RHS FRONT DOOR AND RHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	700.00	\$ 560.00
2	TO DISMANTLE AND RENEW RHS FRONT DOOR AND RHS REAR DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,100.00	\$ 1,000.00
3	TO RESPRAY RHS FRONT DOOR AND RHS REAR DOOR.	\$	2,000.00	\$ 1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 4,992.00	\$ 2,852.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGE 6176 C

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR DOOR - RH	1	\$ 3,039.00	\$	2,431.20
2	REAR DOOR OUTER SEAL - RH	1	\$ 161.00	\$	128.40
3	BONDING AGENT	1	\$ 49.00		
4	CLEANING SOLUTION	1	\$ 68.00		
5	APPLICATOR	1	\$ 8.00		
6	REAR DOOR ATTACHMENT PARTS	1	\$ 129.00		
7	REAR DOOR CATCH - RH	1	\$ 94.00		
8	FRONT DOOR - RH	1	\$ 3,265.00	\$	2,612.00
9	FRONT DOOR OUTER SEAL - RH	1	\$ 179.00	\$	142.80
10	BONDING AGENT	1	\$ 51.00		
11	CLEANING SOLUTION	1	\$ 74.00		
12	APPLICATOR	1	\$ 8.00		
13	FRONT DOOR ATTACHMENT PARTS	1	\$ 252.00		
14	FRONT DOOR CATCH - RH	1	\$ 105.00		
15	TYRE PRESSURE DATA PLATE	1	\$ 34.00	\$	26.96
16	SUNDRIES		\$ 300.00	\$	11.04
TOTAL SPARE PARTS		:	\$ 7,816.00	\$	5,352.40
TOTAL LABOUR CHARGES		:	\$ 4,992.00	\$	2,852.00
GRAND TOTAL		:	\$ 12,808.00	\$	8,204.40

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-30/03/22

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT