

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 18-Jan-22

INSURANCE: _____

MODEL: HYUNDAI IONIC

VEHICLE NO.: SHC 8700A

Description	Qty	List Price	Amount
Front Bumper Cover	1	\$ 418.30	\$ 418.30
Front Bumper Bracket Top (LH)	1	\$ 35.00	\$ 35.00
Front Bumper Bracket (LH)	1	\$ 28.00	\$ 28.00
Front Bumper Retainer Mounting (LH)	1	\$ 65.30	\$ 65.30
Front Bumper Clips 10 pcs	1	\$ 25.00	\$ 25.00
Headlamp(LH)	1	\$ 3,987.30	\$ 3,987.30
Frt Pillar Upper Cover - outer (LH)	1	\$ 89.60	\$ 89.60
Front Fender(LH)	1	\$ 490.70	\$ 490.70
Front Fender Apron Panel (LH)	1	\$ 756.20	\$ 756.20
Front Fender Apron Panel Upper(LH)	1	\$ 329.00	\$ 329.00
Front Fender Shield (LH)	1	\$ 164.70	\$ 164.70
Frt Door(LH)	1	\$ 1,797.20	\$ 1,797.20
Frt Door Rubber	1	\$ 250.00	\$ 250.00
Front Door Regulator (LH)	1	\$ 750.40	\$ 750.40
Front Door Power Motor, LH	1	\$ 689.20	\$ 689.20
Front Door Hinge Upper (LH)	1	\$ 165.76	\$ 165.76
Front Door Hinge Lower (LH)	1	\$ 153.70	\$ 153.70
Front Door Check (LH)	1	\$ 72.98	\$ 72.98
Front Door Inner Lock (LH)	1	\$ 385.60	\$ 385.60
Front Door Outer Handle (LH)	1	\$ 234.80	\$ 234.80
Front Door Mirror ASSY (LH)	1	\$ 1,691.70	\$ 1,691.70
Front Door Trim Board (LH)	1	\$ 796.80	\$ 796.80
Front Door Protector(LH)	1	\$ 186.20	\$ 186.20
Front Door Wire (LH)	1	\$ 869.80	\$ 869.80
speaker	1	\$ 256.10	\$ 256.10
Rear Door (LH)	1	\$ 1,789.90	\$ 1,789.90
Rear Door Outer Handle (LH)	1	\$ 124.80	\$ 124.80
Rear Door Gear/Regulator(LH)	1	\$ 367.84	\$ 367.84
Rear Door Power Motor (LH)	1	\$ 256.80	\$ 256.80
Rear Door Lock Assy	1	\$ 306.40	\$ 306.40
Rear Door Hinge Upper (LH)	1	\$ 173.88	\$ 173.88
Rear Door Hinge Lower (LH)	1	\$ 170.50	\$ 170.50
Rear Door Check(LH)	1	\$ 85.92	\$ 85.92
Rear Door Trim Board (LH)	1	\$ 613.60	\$ 613.60
Rear Door Protector(LH)	1	\$ 166.20	\$ 166.20
Rocker Panel Outer Garnish	1	\$ 715.60	\$ 715.60
Rocker Panel Outer Garnish Clip	1	\$ 65.00	\$ 65.00
Front Wheel Rim (LH)	1	\$ 1,124.20	\$ 1,124.20
Front Wheel Hub Cap and hub assy (LH)	1	\$ 678.50	\$ 678.50
Front Wheel Hub Cap	1	\$ 346.40	\$ 346.40
Front Shock Absorber(Assy)(LH)	1	\$ 372.50	\$ 372.50
Front Shock Absorber Mounting (LH)	1	\$ 372.50	\$ 372.50
Front Drive Shaft (LH)	1	\$ 1,136.70	\$ 1,136.70

Rack & Pinion Assy		1	\$ 2,387.40	\$ 2,387.40
STG Tie Rod		1	\$ 125.60	\$ 125.60
STG Tie End		1	\$ 94.70	\$ 94.70
Stabilizer Bar		1	\$ 326.80	\$ 326.80
Stabilizer Bar Link		1	\$ 92.10	\$ 92.10
Front Suspension Lower Arm (LH)		1	\$ 596.80	\$ 596.80
Knuckle Arm (LH)		1	\$ 663.60	\$ 663.60
ABS Sensor		1	\$ 290.00	\$ 290.00
Rear Fender(LH)		1	\$ 1,768.30	\$ 1,768.30
Rear Fender SHIELD REAR PIECE (LH)		1	\$ 173.60	\$ 173.60
Rear Fender SHIELD Frt Piece (LH)		1	\$ 165.50	\$ 165.50
Rear Tyre Rim (LH)		1	\$ 1,124.20	\$ 1,124.20
Rear Wheel Hup-Cap (LH)		1	\$ 346.40	\$ 346.40
Rear Wheelbearing & Hub assy		1	\$ 554.00	\$ 554.00
Rear Trailing Arm(LH)		1	\$ 265.40	\$ 265.40
Rear Assist (LH)		1	\$ 227.90	\$ 227.90
Rear shock Absorber(LH)		1	\$ 230.50	\$ 230.50
Rear Crossmember		1	\$ 1,468.70	\$ 1,468.70
Stabilizer Bar		1	\$ 387.30	\$ 387.30
Stabilizer Link (LH)		1	\$ 147.30	\$ 147.30
Rear Upper Arm(LH)		1	\$ 239.50	\$ 239.50
Rear Lower Arm(LH)		1	\$ 393.10	\$ 393.10
Rear Knuckle Arm (LH)		1	\$ 538.10	\$ 538.10
SUB TOTAL				\$ 36,163.38
LESS 20%				\$ 7,232.68
DISCOUNTED TOTAL				\$ 28,930.70
Emblem-Blue Drive (LH)	SN	1	\$ 26.60	\$ 26.60
Front Door Comfort Logo (LH)	SN	1	\$ 75.00	\$ 75.00
Front Door Advertisement Logo (LH)	SN	1	\$ 100.00	\$ 100.00
Rear Door Advertisement Logo (LH)	SN	1	\$ 100.00	\$ 100.00
Rear Door Tel No.Sticker(LH)	SN	1	\$ 10.00	\$ 10.00
Rear Door Comfortdelgro & Apps Sticker(LH)	SN	1	\$ 80.00	\$ 80.00
Front Tyre(LH)	SN	1	\$ 216.00	\$ 216.00
Rear Tyre(LH)	SN	1	\$ 216.00	\$ 216.00
SUB TOTAL				\$ 823.60
Labour Charge				
Panel Beating		1	\$1,800.00	\$1,800.00
Spray Painting Charge		1	\$2,000.00	\$2,000.00
Wiring Charge		1	\$100.00	\$100.00
Tuff Kote		1	\$100.00	\$100.00
Towing Charge		1	\$80.00	\$80.00
Remove/Refix Cushion & Upholstery Rear		1	\$150.00	\$150.00
Remove/Refix Undercarriage (RR)		1	\$400.00	\$400.00
Re-set Rear ABS System		1	\$400.00	\$400.00
Remove/Refix Fuel Tank		1	\$80.00	\$80.00
Remove/Refix Exhaust Pipe		1	\$80.00	\$80.00
Transfer of Door Mechanism FRONT		1	\$80.00	\$80.00
Re-set Frt Power Window System		1	\$200.00	\$200.00
Transfer of Door Mechanism REAR		1	\$80.00	\$80.00
Re-set Rear Power Window System		1	\$200.00	\$200.00

Four Wheel Alignment	1	\$120.00	\$120.00
Remove/Refix Undercarriage (Frt)	1	\$400.00	\$400.00
Re-set Frt ABS System	1	\$200.00	\$200.00
Remove/Refix Radiator	1	\$90.00	\$90.00
Remove/Refix Aircon & Refill Gas	1	\$130.00	\$130.00
Diagnostic & Resetting To Erase Fault Code	1	\$550.00	\$550.00
TOTAL LABOUR			\$7,240.00
ESTIMATE TOTAL			\$ 36,994.30
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance			