



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987			S1000026 / ICECICS		M/S Grab Rentals Pte Ltd 6 Battery Road #38-04 Singapore 049909 Work: 65703925		
			Document No. 0				
			Document Date 18/01/2022				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZVW50R	AHXEBW Q3	03/05/2017	SLN4222J	0	12809	75/DS/SLN4222J
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTDKB3FU503556477		2ZRS041023	60	Ng Mei Yen	--/--/----		0.00 --/--/----
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP VEH NO.:SGW8273Y ACC DATE:17/01/22 DRIVE IN: EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				100.00	
2	B	BP-LAB2 CHECK WIRING & CONDUCT LEAK TEST				180.00	
3	S	BP-SUBLET RESET ECU UPON COMPLETION OF REPAIR				180.00	
4	B	BP-LAB2 DRILL HOLE & INSTALL REVERSE SENSOR				180.00	
5	B	BP-LAB2 REPL ACC AFF AREA STRAIGHTEN & PANEL BEAT ACC AFF AREA				3600.00	
6	B	BP-RES2 RESPRAY ACC AFF AREA				2360.00	
7	1	U52159-47913 COVER, RR BUMPER	1.00	469.50		469.50	
8	2	U52575-47040 RETAINER, RR BUMPER	1.00	124.90		124.90	
9	3	U52576-47040 RETAINER, RR BUMPER	1.00	123.60		123.60	
10	4	U52023-47030 REINFORCEMENT	1.00	353.10		353.10	
11	5	U52591-47050 SEAL, RR BUMPER	1.00	93.50		93.50	
12	6	U52592-47040 SEAL, RR BUMPER	1.00	93.50		93.50	
13	7	U52565-47900 FILLER, RR BUMPER	1.00	131.10		131.10	
14	8	U52566-47900 FILLER, RR BUMPER	1.00	131.10		131.10	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts		Less
					Labour		
					Sublet		
					Lubrication/Fluid		Amount Due
					Others		

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details			
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987			S1000026 / ICECICS		M/S Grab Rentals Pte Ltd 6 Battery Road #38-04 Singapore 049909 Work: 65703925			
			Document No. 0					
			Document Date 18/01/2022					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2017	ZVW50R	AHXEBW Q3	03/05/2017	SLN4222J	0	12809	75/DS/SLN4222J	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTDKB3FU503556477		2ZRS041023	60	Ng Mei Yen	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
15	9	U52453-47010 GUARD, RR BUMPER,			1.00	611.30		611.30
16	0	U58307-47090 PANEL SUB-ASSY, BODY			1.00	689.70		689.70
17	1	U76801-47110 A1 GARNISH SUB-ASSY,			1.00	984.40		984.40
18	2	U75403-48010 EMBLEM SUB-ASSY,			1.00	76.00		76.00
19	3	U75441-47130 PLATE, LUGGAGE COMPT			1.00	58.00		58.00
20	4	U75442-47130 PLATE, LUGGAGE COMPT			1.00	58.00		58.00
21	5	U81551-47283 LENS & BODY, RR			1.00	479.30		479.30
22	6	U81561-47153 LENS & BODY, RR			1.00	469.90		469.90
23	7	U81581-47011 LENS & BODY, RR			1.00	532.00		532.00
24	8	U81591-47011 LENS & BODY, RR			1.00	532.00		532.00
25	9	TREVSE-TEFM2 070 2PT R SENSOR WITH ANGLE 070 WH			1.00	101.05		101.05
For & on behalf of		Customer's Signature		Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd						12,711.95		
		Please acknowledge receipt of vehicle		Parts 6,111.95		GST 7.00% 889.84		
				Labour 6,420.00		Less 0.00		
				Sublet 180.00				
				Lubrication/Fluid 0.00				
				Others 0.00		Amount Due 13,601.79		

Customer Copy