



Case Details

Case Reference Number : TAX/01/22/2029
Type of Repair : Accident Repair
Vehicle Registration Number : SHB388B

Company Type : Strides Taxi Pte Ltd
Estimation ID : EST-17246-ID
Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
Accident Date and Time : 17/01/2022 12:50 AM
Vehicle Age(In Months) : 87

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			DOOR RR/RH	1	954.50	954.50	25.00	715.88	Replace	1	0	Repair	R
Standard	Main			DOOR LOCK RR/RH	1	709.30	709.30	25.00	531.97	Replace	0	0	Not Give	Xan
Standard	Main			DOOR REGULATOR MOTOR FRONT RH	1	947.80	947.80	10.00	853.02	Replace	0	0	Not Give	Xan
Standard	Main			CHECK ASSY, RR DOOR,	1	150.30	150.30	25.00	112.73	Replace	0	0	Not Give	Xan
Standard	Main			DOOR OUTER HANDLE RR/RH	1	69.80	69.80	25.00	52.35	Replace	0	0	Not Give	Xan
Total Spare Part Cost									2,265.95		Surveyor Total		0.00	
Lump Sum Discount (%)									30.00		Lump Sum Dis (%)		20	
Final Spare Part Cost									1,549.52		Final Sur Total		0.00	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR RHS PORTION	507.00	200	
Total:			507.00	200.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR DOOR RH	378.00	200	
Total:			936.00	200.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: