

# JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit  
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778  
E-mail:jlperfectautowork@gmail.com



DATE : 18.01.22

TO : **ERGO** MOTOR CLAIMS DEPTS  
VEHICLE NO : **SMN1968Z**  
MODEL : **TOYOTA HARRIER**  
DATE OF ACCIDENT : 18.01.22  
TIME OF ACCIDENT : 07:40HRS

ITEZB36H90J004519

Veron.

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

## CLAIM DETAIL : PARTS

| S/N | DESCRIPTION                              | QTY | UNIT LIST PRICE | TOTAL LIST PRICE |
|-----|------------------------------------------|-----|-----------------|------------------|
| 1   | TAILGATE <i>Dented</i>                   | 1   | \$ 2,378.60     | \$ 2,378.60      |
| 2   | TAILGATE HINGE <i>new</i>                | 2   | \$ 89.30        | \$ 178.60        |
| 3   | TAIL GATE LAMP <i>new</i>                | 2   | \$ 494.40       | \$ 988.80        |
| 4   | TAIL GATE APRON GARNISH <i>new</i>       | 1   | \$ 1,120.60     | \$ 1,120.60      |
| 5   | TAILGATE LOGO <i>new</i>                 | 1   | \$ 85.00        | \$ 85.00         |
| 6   | TAILGATE LOGO BASE GARNISH <i>new</i>    | 1   | \$ 84.50        | \$ 84.50         |
| 7   | TAILGATE EMBLEM 'HARRIER' <i>new</i>     | 1   | \$ 75.00        | \$ 75.00         |
| 8   | TAILGATE EMBLEM 'TURBO'                  | 1   | \$ 68.00        | \$ 68.00         |
| 9   | TAILGATE INNER LOCK <i>Dented</i>        | 1   | \$ 954.40       | \$ 954.40        |
| 10  | TAILGATE WEATHER STRIP <i>new</i>        | 1   | \$ 353.40       | \$ 353.40        |
| 11  | TAILGATE STOPPER <i>new</i>              | 4   | \$ 25.70        | \$ 102.80        |
| 12  | TAILGATE INNER TRIM (LOWER) <i>new</i>   | 1   | \$ 1,075.00     | \$ 1,075.00      |
| 13  | TAILGATE NUMBER PLATE LAMP <i>new</i>    | 2   | \$ 138.60       | \$ 277.20        |
| 14  | TAIL GATE DAMPER <i>new</i>              | 2   | \$ 211.40       | \$ 422.80        |
| 15  | TAILGATE DETECTOR <i>Dented</i>          | 1   | \$ 489.70       | \$ 489.70        |
| 16  | REAR BUMPER (UPPER) <i>new</i>           | 1   | \$ 1,381.75     | \$ 1,381.75      |
| 17  | REAR BUMPER (LOWER) <i>new</i>           | 1   | \$ 744.50       | \$ 744.50        |
| 18  | REAR BUMPER CORNER RETAINER <i>new</i>   | 2   | \$ 95.00        | \$ 190.00        |
| 19  | REAR BUMPER SIDE RETAINER <i>new</i>     | 2   | \$ 55.00        | \$ 110.00        |
| 20  | REAR BUMPER SPONGE <i>new</i>            | 1   | \$ 359.20       | \$ 359.20        |
| 21  | REAR BUMPER REFLECTOR <i>new</i>         | 2   | \$ 89.30        | \$ 178.60        |
| 22  | TAIL LAMP <i>new</i>                     | 2   | \$ 689.60       | \$ 1,379.20      |
| 23  | REAR END PANEL <i>Dented</i>             | 1   | \$ 795.30       | \$ 795.30        |
| 24  | REAR END PANEL TOP GARNISH <i>new</i>    | 1   | \$ 395.40       | \$ 395.40        |
| 25  | REAR END PANEL DAMPER <i>new</i>         | 1   | \$ 1,343.70     | \$ 1,343.70      |
| 26  | REAR END PANEL DAMPER BRACKET <i>new</i> | 2   | \$ 272.10       | \$ 544.20        |

1850

534

731

755

89.30

1507



TO : **ERGO** MOTOR CLAIMS DEPTS  
 VEHICLE NO : **SMN1968Z**  
 MODEL : **TOYOTA HARRIER**  
 DATE OF ACCIDENT : 18.01.22  
 TIME OF ACCIDENT : 07:40HRS

|    |                                           |   |           |             |
|----|-------------------------------------------|---|-----------|-------------|
| 27 | REAR TOOLS COMPARTMENT (INNER)            | 2 | \$ 697.40 | \$ 1,394.80 |
| 28 | REAR TOOLS COMPARTMENT COVER              | 2 | \$ 758.60 | \$ 1,517.20 |
| 29 | REAR SIDE TOOLS COMPARTMENT GARNISH       | 2 | \$ 481.20 | \$ 962.40   |
| 30 | REAR TOOLS COMPARTMENT COVER BOARD (SIDE) | 2 | \$ 189.60 | \$ 379.20   |
| 31 | REAR EXHAUST GASKET                       | 1 | \$ 28.00  | \$ 28.00    |
| 32 | REAR EXHAUST BOX                          | 1 | \$ 896.60 | \$ 896.60   |
| 33 | REAR EXHAUST INSULATOR                    | 1 | \$ 238.20 | \$ 238.20   |
| 34 | REAR EXHAUST MOUNTING                     | 4 | \$ 39.10  | \$ 156.40   |

+ Tools tray behind 685 ✓

TOTAL PRICE \$ 21,649.05  
 LESS 25% \$ 5,412.26  
 SUB TOTAL PRICE \$ 16,236.79

| S/N | DESCRIPTION                            | QTY | UNIT S/NETT | TOTAL S/NETT |
|-----|----------------------------------------|-----|-------------|--------------|
| 1   | REAR NUMBER PLATE                      | 1   | \$ 80.00    | \$ 80.00     |
| 2   | REAR BUMPER CLIP (SET)                 | 1   | \$ 80.00    | \$ 80.00     |
| 3   | REAR BUMPER FOOT 'ACTIVATED STICKER'   | 1   | \$ 120.00   | \$ 120.00    |
| 4   | TAILGATE INNER TRIM (LOWER) CLIP (SET) | 1   | \$ 50.00    | \$ 50.00     |
| 5   | TAILGATE WINDSCREEN SEALANT            | 1   | \$ 80.00    | \$ 80.00     |
| 6   | TAILGATE WINDSCREEN INNER SHIELD       | 1   | \$ 60.00    | \$ 60.00     |
| 7   | TAILGATE AUTO SYSTEM (SPECIAL TYPE)    | 1   | \$ 1,800.00 | \$ 1,800.00  |
| 8   | TAILLAMP CLIP (SET)                    | 1   | \$ 60.00    | \$ 60.00     |
| 9   | REAR FENDER INNER TRIM CLIP (SET)      | 1   | \$ 80.00    | \$ 80.00     |
| 10  | REAR FENDER INNER COWLING CLIP (SET)   | 1   | \$ 80.00    | \$ 80.00     |
| 11  | REAR END PANEL TOP GARNISH CLIPS (SET) | 1   | \$ 30.00    | \$ 30.00     |
| 12  | REAR END PANEL INSULATION SEAL         | 1   | \$ 150.00   | \$ 150.00    |
| 13  | REVERSE CAMERA                         | 1   | \$ 550.00   | \$ 550.00    |

210

TOTAL \$ 3,220.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

| S/N | JOB DESCRIPTION                         | PRICE       | ADJUSTED COST |
|-----|-----------------------------------------|-------------|---------------|
| 1   | TO PANEL BEAT, REMOVE AND REPLACE PARTS | \$ 1,800.00 | 1000          |
| 2   | TO SPRAY PAINT AFFECTED AREA            | \$ 1,800.00 | 1000          |
| 3   | TUFF COAT                               | \$ 250.00   | 60            |
| 4   | WIRING AND BULB CHECK                   | \$ 180.00   | 30            |

TO : **ERGO** MOTOR CLAIMS DEPTS  
 VEHICLE NO : **SMN1968Z**  
 MODEL : **TOYOTA HARRIER**  
 DATE OF ACCIDENT : 18.01.22  
 TIME OF ACCIDENT : 07:40HRS

|    |                                                                                                |           |    |
|----|------------------------------------------------------------------------------------------------|-----------|----|
| 5  | REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR                    | \$ 350.00 | 80 |
| 6  | REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING                                           | \$ 80.00  | 50 |
| 7  | REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING                                           | \$ 80.00  | 50 |
| 8  | REMOVE AND REFIX REAR CAR VIDEO RECORDER                                                       | \$ 80.00  | 50 |
| 9  | CONDUCT WATER LEAKAGE TEST                                                                     | \$ 180.00 | x  |
| 10 | TRANSFER TAILGATE MECHANISM                                                                    | \$ 80.00  | ✓  |
| 11 | REMOVE AND REFIX TAILGATE WINDSCREEN                                                           | \$ 120.00 | ✓  |
| 12 | RESET TAILGATE SYSTEM                                                                          | \$ 250.00 | x  |
| 13 | TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC. | \$ 380.00 | x  |

**TOTAL \$ 5,630.00**

# **ESTIMATE REPORT**

TOTAL PARTS COST : \$ 19,456.79  
 TOTAL LABOUR COST : \$ 5,630.00  
 TOTAL REPAIR COST : \$ 25,086.79

**NB:** THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.  
**PARTS PRICES ARE SUBJECT TO CHANGES.**

YOURS FAITHFULLY,

**IRENE**  
 SERVICE ADVISOR  
 ABBY  
 HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj  
 r/s 19/01/22  
 06 Days

total: 1075878  
 r/s: 8/61c

8/61c