



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CS3/CTI21006959/Avy3e2-1 Date: 14/03/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	SGL 3060K	
Policy No.		Coverage (\$)	0.00	
Claim No.	SNE21D200047	Excess (\$)	0.00	
Assign From	PENG PENG	Assign Date	19/01/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA RUSH	c.c	1495	
Engine No.	HIDDEN	Year of Reg.	2006	
Chassis No.	J200E0006436	Colour	BLACK	
Odometer	261795 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/65 R15	TOURADOR	6 mm	
L/H Front Tyre	215/65 R15	TOURADOR	6 mm	
R/H Rear Tyre	215/65 R15	TOURADOR	6 mm	
L/H Rear Tyre	215/65 R15	TOURADOR	6 mm	
4. Description of Damages				
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.				
5. General Information				
Accident Date	14/06/2021	Inspection Date	18/02/2022	
Survey held at	ACE AUTOLUTION PTE LTD 13 KAKI BUKIT ROAD 4 #03-29 BARTLEY BIZ CENTRE SINGAPORE 417807			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	