

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

17-Jan-22

Our ref : TP/5080/22

Yafaridah Binte Mohd

TP A16.
Ashes.

RE : Estimate cost for vehicle no : SDZ 8189C

1 pc	rear bumper	Dehd	\$	1,500.71	nett	—
1 pc	rear bumper lower spoiler	Dehd		399.76	—	
4 pcs	rear bumper reverse sensor	2 pieces damaged		869.00	434.50	
1 pc	rear bumper reinforcement	Dented.		600.79	✓	
2 pcs	rear bumper retainer	2 pcs		199.74	+	
2 pcs	rear bumper reflector short	2 pcs		128.30	6415.4	
2 pcs	rear bumper reflector long	2 pcs		261.54	130.77	
1 pc	rear bumper tow hook cover	Dehd		75.60	✓	3431.92
1 pc	rear bumper centre holder	Cracked.		289.79	✓	
1 pc	end panel	Regis		1,111.76	+	3088.72
				5,436.99		
less 10%				543.69		
				4,893.30		
Panel beating.				600.00	300	200
Spray painting.				800.00	400	
				6,293.30		
Plus 7%GST				440.53		
				6,733.83		

SD : six thousand seven hundred thirty-three & cents eighty-three only.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Adrian Lj.
P/P 17/01/22.

03 Ryp.

total: 3788.72
(P/P)