



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No.

SKX5322G VOLKSWAGEN SPORTSVAN 1.4 AT AM13HZ CL

Page No. 1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)		SURVEYOR'S ADJUSTMENT		
<u>PARTS (LIST ITEMS)</u>							
1	Rear bumper / BR	NA	1678.00		1331.63		
2	Rear bumper side bracket LH/RH @2*\$101 ? X		202.00				
1	Rear reinforcement ? X nn		678.00				
2	Rear reverse sensor Qty:02*\$201 (LH) ? / BR		402.00		200 /		
1	Boot lid emblem "TSI" / MC		134.00		/		
1	Boot lid emblem "Bluemotion" / MC		124.00		/		
1	Rear bumper center top bracket ? X nn		181.00				
1	Boot lid (Repair refer to labour) X R		0.00				
Part Items Total:			-10%	3399.00			
				-339.90			
				3059.10			
<u>SPECIAL NETT ITEMS</u>							
1	Rear bumper clips		35.00		30 MC		
SN Items Total:			35.00				
Total Parts			3094.10				

1789.30
-10%
1610.37

30

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SKX5322G VOLKSWAGEN SPORTSVAN 1.4 AT AM13HZ CL

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
1	LABOUR To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	800.00	200
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	600.00	400
3	To perform anti-rust treatment on affected areas	60.00	30
4	To remove and repair/refit wiring system at accident damaged area and check for all electrical proper function	60.00	30
5	To remove and replace rear reverse sensor	100.00	30
Labour Total :		1620.00	
TOTAL (PARTS & LABOUR):		4714.10	

690

Steve (LKK)
25/1/22, 11.30am

WZ AL
3 djs
LH
AL

= 233037
4/8 - 1864.99
= 1850