

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22000688/UQY3N2**Date:** 25/03/2022REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNW00013042100

**Claimant Vehicle No :** SKD426D **Insured Vehicle No :** SMV4822Z

Date of Loss: 14/01/2022 Nature of Claim: TP Claim No: SNM22D200390/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKD426D**

Make & Model: HONDA FIT, 1.3 (A) Engine No: L13A4156724

Reg. Date: 24/10/2011 (Man. Year: 2008) Chassis No: GE61144657

Colour: Grey Odometer: 119213 km

Engine Capacity: 1339 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/50R16 Rear Tyre Size: 205/50R16

Front Left Side: Hankook 6 mm Rear Left Side: Hankook 6 mm

Front Right Side: Hankook 6 mm Rear Right Side: Hankook 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,473.36	1,100.00	373.36	25.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,200.00	530.00	670.00	55.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>2,673.36</b>	<b>1,630.00</b>	<b>1,043.36</b>	<b>39.03</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,300.00</b>		
<b>(S\$)</b>	2,673.36	1,300.00	1,373.36	51.37
<b>+ GST 7.00/7.00% (S\$)</b>	187.14	91.00	96.14	51.37
<b>Nett Amount (S\$)</b>	<b>2,860.50</b>	<b>1,391.00</b>	<b>1,469.50</b>	<b>51.37</b>

INSPECTION

Date of Assignment: 20/03/2022

Date Inspected: 19/01/2022 Inspected At: Precise Auto Service (HQ)  
No 1 Kaki Bukit Ave 6, #02-34/36  
Singapore 417883

Estimated Period of Repair: 3.0 days

**Adjuster:** MARCUS CHUA**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 24 Mar 2022)
<b>Parts:</b> 144	HONDA FIT 1.3 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SKD426D)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	2		*REAR BUMPER SIDE RETAINER	Not Necessary	29.60 FL	*- FL	
2	6		*REAR BUMPER CLIPS	Not Necessary	24.60 FL	*- FL	
3	1		*SET REAR BUMPER (ACC)	Cracked	900.00 FS	*900.00 FS	
4	1		*REAR BUMPER CENTER WIRE MESH	Not Necessary	150.00 FS	*- FS	
5	1		*SET REVERSE SENSOR WITH CONTROL UNIT	Shorted	380.00 FS	*200.00 FS	
					<b>Sub Total (S\$)</b>	<b>1,484.20</b>	<b>1,100.00</b>
					<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	10.84	0.00
					<b>Total Parts (S\$)</b>	<b>1,473.36</b>	<b>1,100.00</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE & REFIX REVERSE SENSOR	New	150.00	50.00
2	TO RESPRAY AFFECTED AREAS	New	550.00	280.00
3	TO RENEW DAMAGED PARTS,STRAIGHTEN & REPAIR REAR END PANEL & ALIGNED ALL PARTS	New	500.00	200.00
			<b>Gross Labour Cost (\$)</b>	<b>530.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >