

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLP9243E

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	/
2	RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	110.00	/
3	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	X
4	ZZ/001	CHECK LIGHTING	48.00	/
5	ZZ/002	REPAIR RR END PANEL & RENEW RR BUMPER	560.00	/
6	ZZ/003	S/PAINT RR BUMPER(2TONE) & RR END PANEL	750.00	625
TOTAL LABOUR CHARGES			1688.00	

280 x 2
 125 + 250 + 750

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLP9243E

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
1	BRACKET-BMFR LH X <i>no</i>	85221-4EA0A	38.90		
2	BRACKET-BMFR RH / <i>BR</i>	85220-4EA0A	38.90 /		
3	STAY ASSY-RH X <i>no</i>	H5210-4EAMA	141.00		
4	STAY ASSY-LH X <i>no</i>	H5211-4EAMA	141.00		
5	REINF-BUMPER RR X <i>no</i>	H5030-4EAMA	691.50		
6	ENERGY ABSORBER X <i>no</i>	85090-4EA0B	155.60		
7	FINISHER-REAR B / <i>CVT</i>	85071-4EA0A	18.80 /		
8	CLIP(1.3X10) / <i>MC</i>	01553-05933	13.00 /		
9	CANOE(7.1X2) / <i>MC</i>	76882-0M000	14.20 /		
10	CLIP(8X3) / <i>MC</i>	85284-JD00A	24.00 /		
11	CROMMET(2.7X2) / <i>MC</i>	63846-5V000	5.40 /		
12	FASCIA-RR BUMP / <i>no</i>	85022-4EA0H	876.40 /		
13	SUNDRIES	NPN			20 / 30.00
14	SENSOR-REVERSE / <i>SLH</i>	SENSOR			250.00 /
SUB TOTAL			2158.70	0.00	280.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			431.74	0.00	0.00
GRAND TOTAL			1726.96	0.00	280.00
OVERALL TOTAL			2006.96		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

IAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLP9243E

TOTAL LABOUR CHARGES	1668.00
TOTAL SPARE PARTS CHARGES	2006.96
GRAND TOTAL	3694.96 *

* All charges do not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

Stave (LKK) 20/1/22, 3.00pm
Mr AL
PIP
By BL sy
4 djs

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: