

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/ZHR/0010/2022
DATE : 08-JAN-2022

DS => Steve (JKK Auto)

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
S(079909)
TEL : 63896111
FAX : 62247175

ZHR

OWNER'S NAME : MS YAP BEE LENG
ADDRESS : BLK 51 CHOACHU KANG LOOP
#11-27
S(689682)
TELEPHONE NO : 90108890

Recommend Repair 4 Days

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-SJT9837U
VEHICLE NO : SLP9243E
MODEL CODE : FRLARBZJ11UEA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2
ENGINE NO : HRA2443087A
CHASSIS NO : SJNFEAJ11UZ015673
MILEAGE : 1 KM
DATE IN : 08/01/2022
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : MUHAMMAD ZUHRI
ACCIDENT DATE : 05/01/2022

Lou => \$50 x 4 days

=> \$200.00

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLP9243E

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	120.00
2	RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	110.00	110.00
3	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	.00
4	ZZ/001	CHECK LIGHTING	48.00	48.00
5	ZZ/002	REPAIR RR END PANEL & RENEW RR BUMPER	560.00	560.00
6	ZZ/003	S/PAINT RR BUMPER(2TONE) & RR END PANEL	750.00	625.00
TOTAL LABOUR CHARGES			1688.00	1463.00

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLP9243E

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
			NETT	LIST	S/NETT	
1	BRACKET-BMPR LH	85221-4EA0A	38.90			X
2	BRACKET-BMPR RH	85220-4EA0A	38.90			OK
3	STAY ASSY-RH	H5210-4EAMA	141.00			X
4	STAY ASSY-LH	H5211-4EAMA	141.00			X
5	REINF-BUMPER RR	H5030-4EAMA	691.50			X
6	ENERGY ABSORBER	85090-4EA0B	155.60			X
7	FINISHER-REAR B	85071-4EA0A	18.80			OK
8	CLIP(1.3X10)	01553-05933	13.00			OK
9	CANOE(7.1X2)	76882-0M000	14.20			OK
10	CLIP(8X3)	85284-JD00A	24.00			OK
11	CROMMET(2.7X2)	63846-5V000	5.40			OK
12	FASCIA-RR BUMP	85022-4EA0H	876.40			OK
13	SUNDRIES	NPN			20.00	OK
14	SENSOR-REVERSE	SENSOR			250.00	OK
SUB TOTAL			990.70	0.00	270.00	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			198.14	0.00	0.00	
GRAND TOTAL			792.56	0.00	270.00	
OVERALL TOTAL			1062.56			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

911, BUKIT TIMAH ROAD

SINGAPORE 589623

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SLP9243E

NETT ITEM	990.70
LESS 20.00%)	-198.14
NETT AMOUNT	792.56
LIST ITEM	0.00
LESS 30.00%)	0.00
LIST AMOUNT	0.00
SPECIAL NETT ITEM	270.00
LESS .00%)	0.00
SPECIAL NETT AMOUNT	270.00
TOTAL LABOUR CHARGES	1463.00
TOTAL SPARE PARTS CHARGES	1062.56
TOTAL CHARGES	2525.56
ADD 7 % GST	176.79
GRAND TOTAL	2702.35
