

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22000692/AQY3Q2**Date:** 03/11/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00125522102

Claimant Vehicle No : FBQ8271T **Insured Vehicle No :** SMM6013B

Date of Loss: 09/12/2021 Nature of Claim: TP Claim No: SNM21D207181/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBQ8271T**

Make & Model: HONDA CB150R, 149cc Engine No: KC32E0017084

Reg. Date: 25/12/2019 (Man. Year: 2018) Chassis No: MLHKC2886J5017084

Colour: Blue Odometer: 71282 km

Engine Capacity: 149 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 110/70 R17 Rear Tyre Size: 150/60 R17

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,111.93	1,440.56	2,671.37	64.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,090.00	460.00	630.00	57.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,201.93	1,900.56	3,301.37	63.46
Approved Total (Overridden) (\$\$)		1,500.00		
(\$\$)	5,201.93	1,500.00	3,701.93	71.16
+ GST 7.00/7.00% (\$\$)	364.14	105.00	259.14	71.16
Nett Amount (\$\$)	5,566.07	1,605.00	3,961.07	71.16

INSPECTION

Date of Assignment: 24/01/2022

Date Inspected: 20/01/2022 Inspected At: Ms Car Auto Pte Ltd (HQ)
8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT
Singapore 415875

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 02 Nov 2022)	
Parts:	N/A	HONDA CB150R 149cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBQ8271T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP	Cut	285.00 FL	*285.00 FL
2	1		*HEADLAMP COWLING	Cut	85.00 FL	*85.00 FL
3	1		*FRONT FENDER	Repair	175.00 FL	*- FL
4	1		*FORK STEM LH	Necessary	185.00 FL	*185.00 FL
5	1		*FORK WHEEL BEARING	Necessary	75.00 FL	*75.00 FL
6	1		*FORK ASSY LH	Bent	575.00 FL	*575.00 FL
7	1		*FRONT FAIRING	Not Necessary	145.00 FL	*- FL
8	1		*FRONT CENTER COVER	Not Necessary	185.00 FL	*- FL
9	1		*HANDLEBAR	Not Necessary	175.50 FL	*- FL
10	1		*SET HANDLEBAR GRIP	Not Necessary	75.00 FL	*- FL
11	1		*SET HANDLE BAR BALANCER	Not Necessary	75.00 FL	*- FL
12	2		*SIGNAL LIGHT LH	Not Necessary	167.40 FL	*- FL
13	1		*SHROUD LH	Not Necessary	68.30 FL	*- FL
14	1		*MARK SHROUD	Not Necessary	47.80 FL	*- FL
15	1		*RUBBER	Not Necessary	34.30 FL	*- FL
16	1		*HOLDER	Not Necessary	78.30 FL	*- FL
17	1		*ARM COMP LH	Not Necessary	116.50 FL	*- FL
18	1		*BRACKET MAIN STEP	Not Necessary	375.60 FL	*- FL
19	1		*FRONT LEFT FAIRING	Cut	173.40 FL	*173.40 FL
20	1		*REAR LEFT FAIRING	Not Necessary	155.60 FL	*- FL
21	1		*PILLION BRACKET LH	Not Necessary	105.00 FL	*- FL
22	1		*SIDE MIRRORS	Not Necessary	85.00 FS	*- FS
23	1		*TAILBOX	Cut	300.00 FS	*200.00 FS
24	1		*TAILBOX BRACKET	Not Necessary	105.00 FS	*- FS
25	1		*HELMET	Not Necessary	600.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,447.70	1,578.40
- List Item Discount on L Items 10.00/10.00% (\$\$)	335.77	137.84
Total Parts (\$\$)	4,111.93	1,440.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO R&R ACCIDENT DAMAGE PARTS ,TO CUT /WELD KNOCK AND REALIGN ACCIDENT AFFECTED AREA	New	600.00	200.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	New	350.00	200.00
3	TO CHECK WHEEL ALIGNMENT	New	60.00	60.00
4	TO CHECK CHASSIS ALIGNMENT	New	80.00	0.00
Gross Labour Cost (\$\$)			1,090.00	460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >