

**Note: This document has not been finalised.**

# **LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance  
(Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Billy Tan

Date: 01 Nov 2022

## **Preliminary Advice**

Insured : SMM6013B

Vehicle No

TP Vehicle : FBQ8271T  
No

Accident Date : 09/12/2021

Make : HONDA CB150R

Assignment Date : 24/01/2022

Date of : 20/01/2022

Est. Duration of : 4  
Repair

Inspection At : MS CAR AUTO PTE LTD (HQ)  
8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT  
SINGAPORE 415875

## **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross) :S\$ 4,868.93

Revised Amount :S\$ 1,900.56

Check Items (Estimated) :S\$ 0.00

Total :S\$ 1,900.56

Lump Sum Repair :S\$ 1,500.00

## **Total Loss Consideration**

New for Old Value :S\$

Pre-Accident Value :S\$

COE / PARF Rebate :S\$

Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.