

Justin

P/P 2852/10

not Andrew
19/1/22

Vehicle: GBK4797B

Make & Model:

SUZUKI EVERY

4 days

Chassis No:

DA17V-856861

S/N	Parts/Labour	QTY	Unit Price	Price	Recommend
1	Rear Boot			\$ 899.00	Body DO ✓
2	Rear Boot Windscreen Sealant			\$ 60.00 SN	new 405/N
3	Rear Boot Emblem			\$ 38.00	su X
4	Rear Boot Handle			\$ 45.00	11 X
5	Rear Boot "4 Pax" Sticker			\$ 10.00 SN	new ✓ 105/N
6	Rear Boot "70Km/h" Sticker			\$ 10.00 SN	new ✓ 105/N
7	Rear Bumper			\$ 527.00	but ✓
8	Rear Bumper Clips			\$ 30.00 SN	new ✓ 305/N
9	Taillamp (Left & Right)	2	\$85.00	\$ 170.00	su X
10	Rear Licence Plate			\$ 40.00 SN	but ✓ 405/N
11	Rear Licence Plate Lamp			\$ 35.00	11 X
12	Reverse Sensor <i>SENSOR</i>			\$ 200.00 SN	shokid ✓ 2005/N
13	Rear Camera			\$ 120.00 SN	su X
14	Rear End Panel			\$ 220.00	R X
15	Rear Boot Lock		157	\$ 78.00	SVC X
16					
Labour					
1	Transfer Rear Windscreen			\$ 120.00	✓
2	Transfer Boot <i>mechanism</i>			\$ 150.00	60
3	Anti Rust Proof			\$ 100.00	30
4	Check Wiring			\$ 100.00	20
5	Panel Beating			\$ 600.00	580

6	Paint Work			\$ 800.00	500
---	------------	--	--	-----------	-----

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 1426
 152
 P- 1212.10
 S.N- 330.00
 L- 1310
 2852.10