

BEST Solution Autocare Pte Ltd

53 Ubi Avenue 1, #03-01, Paya Ubi Industrial Park, Singapore 408934

Business Reg. No.: 201626438D

☎ 6744 0777

☎ 6744 2377

Estimate Quotation

Quotation No	Jan 002/2022
Date	16/1/2022
Vehicle No	SLZ2064Z
Make / Model	Infiniti Q50

Xiao Tong

JN1BCAV3720570041

To: AXA Insurance Singapore Pte Ltd
Address: 8 Shenton Way #27-01 AXA Tower Singapore 068811

Qty	DESCRIPTION	UNIT	Amount
	Items		
1 pc	front bumper <i>Defect</i>		\$ ✓ 953.00
1 pc	front bumper clip <i>Ne</i>		\$ ✓ 30.00
2 pcs	front bumper side retainer <i>Ne</i>	\$ 65.00	\$ ✓ 130.00
1pc	front grille <i>Cracked</i>		\$ ✓ 698.00
1 pc	front grille chrome garnish <i>Cracked</i>		\$ ✓ 675.00 <i>310</i>
1 pc	front bumper tow hook cover <i>Missing</i>		\$ ✓ 42.00
1 set	front parking sensor <i>Painted</i>		\$ ✓ 350.00
1 pc	n/s front bumper fog lamp <i>Cracked</i>		\$ ✓ 475.00 <i>335</i>
1 pc	n/s front bumper fog lamp garnish <i>Cracked</i>		\$ ✓ 165.00
1 pc	n/s front bumper fog lamp chrome garnish <i>Cracked</i>		\$ ✓ 215.00
1 pc	front number plate <i>Defect</i>		\$ ✓ 60.00
1 pc	front bumper top rubber seal <i>Ne</i>		\$ + 165.00 <i>180</i>
1 pc	front bumper sponge <i>Cracked</i>		\$ ✓ 345.00 <i>722</i>
1 pc	front bumper enforcement <i>Defect</i>		\$ ✓ 989.00 <i>3066</i>
1 pc	o/s headlamp <i>Cracked</i>		\$ ✓ 3,650.00
1pc	o/s air con condenser side cover <i>Ne</i>		\$ + 75.00
1 set	rear bumper clip <i>Ne</i>		\$ ✓ 30.00
1 pc	rear bumper <i>Defect</i>		\$ ✓ 988.00
2pcs	rear bumper side retainer <i>Ne</i>	\$ 65.00	\$ ✓ 130.00 <i>681</i>
1 pc	rear bumper reinforcement bar <i>Defect</i>		\$ ✓ 925.00
1pc	rear number plate <i>Best</i>		\$ ✓ 60.00
1 set	rear bumper reverse sensor (4pcs) <i>Painted 2 pieces</i>	\$ 350.00	\$ <i>700</i> 1,400.00 <i>590</i>
1pc	boot lid <i>Defect</i>		\$ ✓ 1,358.00 <i>1151</i>
1 pc	boot lid w/strip <i>lit</i>		\$ ✓ 185.00
1 pc	boot lid inner lock <i>Defect</i>		\$ ✓ 195.00
1 pc	boot lid lock catch <i>Ne</i>		\$ + 95.00
1pc	boot lid centre emblem <i>Ym</i>		\$ ✓ 89.00
1pc	boot lid Q50 emblem		\$ ✓ 155.00
1pc	rear end panel <i>Defect</i>		\$ ✓ 985.00 <i>895</i>
1pc	rear end panel top garnish <i>Defect</i>		\$ ✓ 285.00
1 set	rear end panel top garnish clip <i>Ne</i>		\$ ✓ 30.00
2 pcs	rear bumper bracket <i>Defect</i>		\$ ✓ 175.00
1 pc	rear lock sensor <i>Painted</i>		\$ ✓ 125.00
2 pcs	tail lamp <i>Cracked</i>		\$ ✓ 1336.00 <i>668</i>
2 pcs	boot lid reflector <i>2x11 Cracked</i>		\$ <i>267.50</i> 515.00
1 pc	boot lid chrome handle <i>Cracked</i>		\$ ✓ 653.00 <i>390</i>

15005.50
13504.95

BEST Solution Autocare Pte Ltd

53 Ubi Avenue 1, #03-01, Paya Ubi Industrial Park, Singapore 408934

Business Reg. No.: 201626438D

☎ 6744 0777

☎ 6744 2377

	Labour Charge		
1	to dismantle damaged parts, panel beat, repair (front)	\$	500 600.00
2	to putty and spray painting on affected area (front)	\$	250 500.00
3	to dismantle damaged parts, panel beat, repair (rear)	\$	800 900.00
4	to putty and spray painting on affected area (rear)	\$	900 1,000.00
5	anti rust	\$	60 100.00
6	wiring check	\$	✓ 50.00
7	check and adjust wheel alignment	\$	✓ 120.00
8	transfer boot lid <i>Refitting</i>	\$	60 80.00
9	remove and repair rear garnish etc	\$	80 250.00
10	reverse sensor	\$	50 80.00
11	remove and refix aircon and regas	\$	✓ 120.00
		Subtotal:	\$ 21,943.00

BEST SOLUTION AUTOCARE PTE LTD

Authorised Signature

Adrian Lim
1/s 20/01/22

10 Days

total: 16254.95

h/s: 13K

13.1K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: