

BEST Solution Autocare Pte Ltd

53 Ubi Avenue 1, #03-01, Paya Ubi Industrial Park, Singapore 408934

Business Reg. No.: 201626438D

☎ 6744 0777

☎ 6744 2377

Estimate Quotation

Quotation No	Jan 002/2022
Date	16/1/2022
Vehicle No	SLZ2064Z
Make / Model	Infiniti Q50

To: AXA Insurance Singapore Pte Ltd

Address: 8 Shenton Way #27-01 AXA Tower Singapore 068811

Qty	DESCRIPTION	UNIT	Amount
	Items		
1 pc	front bumper <i>Defect</i>		\$ ✓ 953.00
1 pc	front bumper clip <i>Ne</i>		\$ ✓ 30.00
2 pcs	front bumper side retainer <i>Ne</i>	\$ 65.00	\$ ✓ 130.00
1 pc	front grille <i>Cracked</i>		\$ ✓ 698.00
1 pc	front grille chrome garnish <i>Cracked</i>		\$ ✓ 675.00
1 pc	front bumper tow hook cover <i>Missing</i>		\$ ✓ 42.00
1 set	front parking sensor <i>Defect</i>		\$ ✓ 350.00
1 pc	n/s front bumper fog lamp <i>Cracked</i>		\$ ✓ 475.00
1 pc	n/s front bumper fog lamp garnish <i>Cracked</i>		\$ ✓ 165.00
1 pc	n/s front bumper fog lamp chrome garnish <i>Cracked</i>		\$ ✓ 215.00
1 pc	front number plate <i>Defect</i>		\$ ✓ 60.00
1 pc	front bumper top rubber seal <i>Ne</i>		\$ ✓ 165.00
1 pc	front bumper sponge <i>Cracked</i>		\$ ✓ 345.00
1 pc	front bumper enforcement <i>Defect</i>		\$ ✓ 989.00
1 pc	o/s headlamp <i>Cracked</i>		\$ ✓ 3,650.00
1 pc	o/s air con condenser side cover <i>Ne</i>		\$ ✓ 75.00
1 set	rear bumper clip <i>Ne</i>		\$ ✓ 30.00
1 pc	rear bumper <i>Defect</i>		\$ ✓ 988.00
2 pcs	rear bumper side retainer <i>Ne</i>	\$ 65.00	\$ ✓ 130.00
1 pc	rear bumper reinforcement bar <i>Defect</i>		\$ ✓ 925.00
1 pc	rear number plate <i>Defect</i>		\$ ✓ 60.00
1 set	rear bumper reverse sensor (4pcs) <i>Defect 2 pieces</i>	\$ 350.00	\$ ✓ 1,400.00
1 pc	boot lid <i>Defect</i>		\$ ✓ 1,358.00
1 pc	boot lid w/strip <i>lit</i>		\$ ✓ 185.00
1 pc	boot lid inner lock <i>Defect</i>		\$ ✓ 195.00
1 pc	boot lid lock catch <i>Ne</i>		\$ ✓ 95.00
1 pc	boot lid centre emblem <i>Ne</i>		\$ ✓ 89.00
1 pc	boot lid Q50 emblem		\$ ✓ 155.00
1 pc	rear end panel <i>Defect</i>		\$ ✓ 985.00
1 pc	rear end panel top garnish <i>Defect</i>		\$ ✓ 285.00
1 set	rear end panel top garnish clip <i>Ne</i>		\$ ✓ 30.00
2 pcs	rear bumper bracket <i>Defect</i>		\$ ✓ 175.00
1 pc	rear lock sensor <i>Defect</i>		\$ ✓ 125.00
2 pcs	tail lamp <i>Cracked</i>		\$ ✓ 668.00
2 pcs	boot lid reflector <i>Cracked</i>		\$ ✓ 515.00
1 pc	boot lid chrome handle <i>Cracked</i>		\$ ✓ 653.00

BEST Solution Autocare Pte Ltd

53 Ubi Avenue 1, #03-01, Paya Ubi Industrial Park, Singapore 408934

Business Reg. No.: 201626438D

☎ 6744 0777

📠 6744 2377

Labour Charge			
1	to dismantle damaged parts, panel beat, repair (front)	\$ 400	600.00
2	to putty and spray painting on affected area (front)	\$ 250	500.00
3	to dismantle damaged parts, panel beat, repair (rear)	\$ 800	900.00
4	to putty and spray painting on affected area (rear)	\$ 800	1,000.00
5	anti rust	\$ 60	100.00
6	wiring check	\$ ✓	50.00
7	check and adjust wheel alignment	\$ ✗	120.00
8	transfer boot lid <i>Refit</i>	\$ 600	80.00
9	remove and repair rear garnish etc	\$ 60	250.00
10	reverse sensor	\$ 50	80.00
11	remove and refix aircon and regas	\$ +	120.00
Subtotal:		\$	21,943.00

BEST SOLUTION AUTOCARE PTE LTD

Authorised Signature

Adrian L
1/5 20/01/22

10 Days