


ASS. REC. BY: Steve REF: CS/ASM 22000 709/Ety3

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: XE 5992T Yr Regn: 11/11/20
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Traller or
 Make: Mercedes-Benz Arocs c.c. 7698
 Colour White A/C: Insured / Std / NI / NA
 Sp. Reading 42219 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: W1T96401420464256
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modl: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 295/80R22.5
 R: ()

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front Rear
 R/Bal. 4 mm R/Bal. 4 mm
 L/Bal. 4 mm L/Bal. 4 mm
 D.O.A. 13/1/22 D.O.I. 20/1/22
 Survey held at Zenith Engineering
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

SUBMIT \$13700, 10 DAYS

RED: 300;2%

Finalize \$13,700.00 (P/P, before GST).

10 days

Date/Time, File Pass to?

☐ : Prell. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: 10

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

TOTAL

**ZENITH ENGINEERING PTE LTD**

34 Joo Koon Circle, Singapore 629060

Tel: (65) 6861 1100

Fax: (65) 6862 1948

Email: info@ze.com.sg

Website: www.ze.com.sg

CO No: 197904024Z GST Reg No: M2-0037093-7

QUOTATION

NO: QU22-L0054-R01

Customer : SembWaste Pte Ltd
30 Hill Street
#05-04
Singapore 179360
Attn : Finance Dept

Attn : A/C Kristin

Tel : 6266 0416

Fax: 6227 1443

Date : 14/01/22

Validity : 13/02/22

Account No : SE04

Currency : Singapore Dollar

Page : Page 1 of 1

No.	Description	Qty	UOM	Unit Price S\$	Amount S\$
1	Replacement of new binlifter Assy for RCV XE5992T , caused by accident .	1	EA	14,000.00	14,000.00

Supply of labour and material for the repair of RCV XE5992T as follows
removing of damaged binlifter Assy , forming & welding , fabrication of
sub assembly , retrofitting new bin lifter stepper and sensor onto the
RCV and testing and painting of Binlifter assembly of affected area of repair.

*Deduct Salvage \$300***TERMS & CONDITIONS**

Payment : Cash on Delivery

Validity : 30 days from the date of this quotation

Delivery : 14 working days.

PK/cc

*Steve (LKK)**MR R
PIP, My BLK**8322 8813**20/1/22, 11:30am*

Net Amount	:	14,000.00
Add 7% GST	:	980.00
Total Amount	:	14,980.00

10 dys

Ong Poh Kiat
Head of Service Department
68611100



Confirmed & Accepted By:
SembWaste Pte Ltd
Name:
Title:
Date:
Company Stamp: