

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241

Fax: (65) 6741 7276

RCB No.: 53231488C

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident dat : 18/01/2021

19/01/2021

TP Sompō.
Veran.

Estimated repair cost for vehicle no: SJB3888G MERCEDES BENZ E 200CGI

CHASSIS: WDD2120482A349846 (2010)

S/N	Qty	Items	U/price	Amount
1	1	REAR BUMPER TOP <i>Re Horn</i>	\$1,713.00	\$1,713.00 <i>1637</i>
2	1	REAR BUMPER LOWER LIP <i>new</i>	\$819.00	\$819.00 <i>+</i>
3	1	REAR BUMPER SIDE RETAINER <i>could</i>	\$65.00	\$65.00 <i>✓</i>
4	1	REAR BUMPER SIDE BRACKET <i>new</i>	\$165.00	\$165.00 <i>+</i>
5	1	REAR BUMPER CHROME MOULDING RH <i>new</i>	\$225.00	\$225.00 <i>✓</i>
6	1	RH REAR TAILLAMP <i>could</i>	\$1,363.00	\$1,363.00 <i>672</i>
7	1	RH REAR TAILLAMP LOWER BRACKET <i>could</i>	\$182.00	\$182.00 <i>45</i>
8	1	REAR FENDER RH <i>Repair</i>	\$4,023.00	\$4,023.00 <i>+</i>
9	1	REAR FENDER AIR VENT RH <i>new</i>	\$72.00	\$72.00 <i>+</i>
10	1	REAR WINDSCREEN GLASS MOUDLING <i>new</i>	\$285.00	\$285.00 <i>+</i>
			TOTAL :	\$8,912.00
			LESS 10 %	\$891.20
			SUB-TOTAL :	\$8,020.80

2644
23379.6060

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	REAR BUMPER CLIPS <i>new</i>	\$80.00	\$80.00 <i>30</i>
2	1	REAR WINDSCREEN GLASS MOULDING <i>new</i>	\$150.00	\$150.00 <i>+</i>
3	1	REAR TAILLAMP CLIPS RH <i>new</i>	\$30.00	\$30.00 <i>20</i>
			TOTAL:	\$260.00

50

TOTAL PARTS : \$8,280.80

Labour charges

- 1 LABOUR FOR PANEL BEATING
- 2 LABOUR FOR SPRAYPAINTING
- 3 LABOUR FOR REMOVE & REFIX REAR WINDSCREEN GLASS
- 4 WIRING CHECK
- 5 TO APPLY TUFF COATING/RUST PROOF ACCIDENT AREAS

930

350 \$800.00
500 \$800.00
+ \$200.00
30 \$80.00
50 \$300.00
\$2,180.00

Admin
1/5 24/01/22

03 Days

Total:- \$10,460.80

total: 3359600
A/S: 27K

27K

WARRANTY
The Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: