

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG22000715/UVF3E2

Date: 09/03/2022

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 1001424641
Claimant Vehicle No : GBF7469E Insured Vehicle No : YL7196M
Date of Loss: 18/01/2022 Nature of Claim: TP Claim No: 268637

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBF7469E**
Make & Model: MITSUBISHI CANTER, 3.0 D FEA01BR2SDEB (CBU) Engine No: 4P10C47697
Reg. Date: 27/02/2017 (Man. Year: 2016) Chassis No: FEA01BA20492
Colour: White Odometer: 190278 km
Engine Capacity: 2998 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/75 R15 Rear Tyre Size: 195/75 R15 (D)
Front Left Side: Kenda 6 mm Rear Left Side: Kenda 6/6 mm
Front Right Side: Kenda 6 mm Rear Right Side: Kenda 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,500.00	2,880.00	5,620.00	66.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,130.00	900.00	1,230.00	57.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,630.00	3,780.00	6,850.00	64.44
Approved Total (Overridden) (S\$)		3,000.00		
(S\$)	10,630.00	3,000.00	7,630.00	71.78
+ GST 7.00/7.00% (S\$)	744.10	210.00	534.10	71.78
Nett Amount (S\$)	11,374.10	3,210.00	8,164.10	71.78

INSPECTION

Date of Assignment: 21/01/2022
Date Inspected: 20/01/2022 Inspected At: Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50 Autobay
Singapore 417883
Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 04 Feb 2022)

Parts: N/A MITSUBISHI CANTER 3.0 D FEA01BR2SDEB (CBU) (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBF7469E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BACK DOOR O/S	Dented / Bent	1,800.00 F	*1,200.00 F
2	1		*REAR BACK DOOR LOWER HINGE O/S	Bent	450.00 F	*200.00 F
3	1		*SET REAR BACK DOOR CORPORATE STICKER O/S	Necessary	1,000.00 F	*480.00 F
4	1		*REAR CARGO BOX PILLAR O/S	Dented / Bent	1,500.00 F	*1,000.00 F
5	1		*REAR CARGO BOX PILLAR STOPPER O/S	Serviceable	50.00 F	*- F
6	1		*REAR CARGO BOX LOWER PANEL	Repair	900.00 F	*- F
7	1		*REAR CARGO BOX SLIDING DOOR O/S	Repair	1,800.00 F	*- F
8	1		*SET REAR CARGO BOX SLIDING DOOR STICKER O/S	Not Necessary	1,000.00 F	*- F

F=Franchise part.

Total Parts (\$\$) **8,500.00** **2,880.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	0.00
2	TO SPRAY RUST PROOFING	New	80.00	0.00
3	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	800.00	600.00
4	TO PUTTY & SPRAY PAINTING	New	1,200.00	300.00
			Gross Labour Cost (\$\$)	2,130.00
				900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >