Id	<	1	of 2 ?	>	Þ١	$\bigcirc$	<b>⊕</b>	100%	~		<sub>G</sub>	Find   Next	
----	---	---	--------	---	----	------------	----------	------	---	--	--------------	-------------	--



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	ale Des Experts En A	Automob	ile							
	STRIDES AUTOM	OTIVE SERVICES PTE LTD	F	Ref:	CS3/SMR22000718/Vvf3							
	60 WOODLANDS I E4SINGAPORE 75	INDUSTRIAL PARK 57705	1	Date:	20/01/2022							
			(	Code:	SMR							
١.	Policy Particulars :- (THIRD PARTY CLAIM)											
	Insured Veh.	SHD 6339T	Veh. Inspected		SJN 6670J							
	Policy No.		Coverage (\$)		0.00							
	Claim No.	TAX/01/22/2021	Excess (\$)		0.00							
	Assign From	HUA YEN	Assign Date		20/01/2022							
<u>.</u>	Vehicle Particulars & Condition											
	Make & Model		c.c		0							
	Engine No.	HIDDEN	Year of Reg.									
	Chassis No.		Colour									
	Odometer	-	Steering									
	Brakes		Modification									
	General											
3.		Condition	ons of Tyres									
		Size	Make		Balance							
	R/H Front Tyre				mm							
	L/H Front Tyre				mm							
	R/H Rear Tyre				mm							
	L/H Rear Tyre				mm							
		Description of Damages										
j.	General Information											
	Accident Date	13/01/2022	Inspection Date	,	20/01/2022							
	Survey held at				-							
		25 KAKI BUKIT ROAD 4, #01-39	, SYNERGY @ KB,	SINGA	PORE 417800							
a.	Remarks											
-	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.											