

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance
(Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Adeline Chng Pei Wen

Date: 20 Jan 2022

Preliminary Advice

Vehicle No	: SJS7M	Accident Date	: 15/01/2022
Make	: PORSCHE CAYENNE	Policy No.	: DMPCSNW00074102100
Assignment Date	: 20/01/2022	Excess	: S\$4,000.00
Date of Inspection	: 20/01/2022	Est. Duration of Repair	: 7
Inspection At	: MBM WHEELPOWER PTE LTD (SIN MING) 176 SIN MING DRIVE #01-15, SIN MING AUTOCARE SINGAPORE 575721		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$ 42,695.76
Revised Amount	:S\$ 28,090.34
Check Items (Estimated)	:S\$ 7,400.61
Total	:S\$ 35,490.95

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$ 440,000.00
COE / PARF Rebate	:S\$ 147,644.00

Salvage Value	:S\$
Margin for Repair	:S\$ 292,356.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.