

Submitted 20.12.2021

Car In.



CSA Jeffery Koh

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 436180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

Steve (CLKK)
20/12/21, 3:30pm
00-AL1 AL

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 60428 *Excess - \$750* Page No. : 1 of 4
Date Estimated : 28/12/2021 *PIP*
Prepared By : Foong Shih Jye *M7 BL 5/1*

- ESTIMATE REPAIR FOR -
Soh Bee Guat
223 Lorong 8 Toa Payoh
#08-753

- ACCOUNT - 40000
Cash Sales - Service
Singapore

Singapore 310223

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFA3838D	WBA1V720X0V945436	30/07/2018	116d	28200

DESCRIPTION	VALUE
To replace front left side panel and repair inner pillar left	850 / 2,550.00
To spray paint front left side panel and front left A pillar	841 / 1,558.00
To carry out body cavity preservation. (Per panel).	112 / 118.00
To check electrical wiring system at the front section for proper function including adjustment of headlights.	168 / 177.00
Sundries.	40 / 80.00
To check steering geometry and conduct wheel alignment in accordance with BMW specifications. (1x).	504 / 531.00

Total Labour 1: 5,014.00

DESCRIPTION	QTY	PRIC	VALUE
FRT LH FENDER	1	600.25	600.25
FRT LH SIDE PANEL BRACKET 3	1	35.30	35.30
Total Parts			635.55

Labour 1	:	5,014.00
Parts	:	635.55
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	395.47
Grand Total	:	6,045.02



** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Scanned with CamScanner