

Submitted 20.12.2021

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401589W QNT Reg. No. M2-0020081-X
Toll-Free Number (1800-2285269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Tampong Arang Road
East Coast Centre
Singapore 458188
Fax: 63489773

318, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64756601 (AfterSales)
64756624 (Motorrad)

Car In.



CSA Jeffrey Koh

Stew (LKR)
20/12/21, 3:30pm
00-AL AL

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 60428
Date Estimated : 28/12/2021
Prepared By : Foong Shih Jye

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -
Soh Bee Guat
223 Lorong 8 Toa Payoh
#08-753

Singapore 310223

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFA3838D	WBA1V720X0V945436	30/07/2018	116d	28200

DESCRIPTION	VALUE
To replace front left side panel and repair inner pillar left	850 2,550.00
To spray paint front left side panel and front left A pillar	841 1,558.00
To carry out body cavity preservation. (Per panel).	112 118.00
To check electrical wiring system at the front section for proper function including adjustment of headlights.	168 177.00
Sundries.	80.00
To check steering geometry and conduct wheel alignment in accordance with BMW specifications. (1x).	504 531.00

Total Labour 1: 5,014.00

DESCRIPTION	QTY	PRIC	VALUE
FRT LH FENDER	1	600.25	600.25
FRT LH SIDE PANEL BRACKET 3	1	35.30	35.30

Total Parts : 635.55



Labour 1	:	5,014.00
Parts	:	635.55
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	395.47
Grand Total	:	6,045.02

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **
** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **