



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL 64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Ref: CS3/GRB21012724/Evf3e2-1	
			Date: 24/01/2022	
			Code: GRB	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLP 8894H	Veh. Inspected	FBS 9489R	
Policy No.	D21MFL0000447	Coverage (\$)	0.00	
Claim No.	MFL2021D0005203	Excess (\$)	0.00	
Assign From	CARINE KEK PHER SER	Assign Date	20/01/2022	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA AEROX 155 CONNECTED	c.c	155	
Engine No.	HIDDEN	Year of Reg.	2021	
Chassis No.	MH3SG6410MJ048667	Colour	RED	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	70/80-16	BRIDGESTONE	4 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	70/80-16	BRIDGESTONE	4 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/11/2021	Inspection Date	16/12/2021	
Survey held at	ALBERT MOTOR SUPPLY PTE LTD BLK 1008 #01-10, BUKIT MERAH LANE 3, SINGAPORE 159722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	