

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22000730/UQY3N2**Date:** 08/03/2022REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00202852102

**Claimant Vehicle No :** SMP7046J **Insured Vehicle No :** SLK3030T

Date of Loss: 15/01/2022 Nature of Claim: TP Claim No: SNM22D200462/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMP7046J**

Make & Model: TOYOTA CAMRY, 2.0 (A) Engine No: A25A0132608

Reg. Date: 10/10/2019 (Man. Year: 2018) Chassis No: AXVH701026038

Colour: Black Odometer: 87984 km

Engine Capacity: 2487 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                     | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                     | 12,861.97         | 1,913.22          | 10,948.75         | 85.12         |
| Miscellaneous Items                       | 0.00              | 0.00              | 0.00              |               |
| Labour                                    | 3,510.00          | 1,250.00          | 2,260.00          | 64.39         |
| Paintwork Labour                          | 0.00              | 0.00              | 0.00              |               |
| Towing                                    | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (\$\$)</b>      | <b>16,371.97</b>  | <b>3,163.22</b>   | <b>13,208.75</b>  | <b>80.68</b>  |
| <b>Approved Total (Overridden) (\$\$)</b> |                   | <b>2,500.00</b>   |                   |               |
| <b>Nett Amount (\$\$)</b>                 | <b>16,371.97</b>  | <b>2,500.00</b>   | <b>13,871.97</b>  | <b>84.73</b>  |

INSPECTION

Date of Assignment: 20/01/2022

Date Inspected: 20/01/2022 Inspected At: 15 KAKI BUKIT ROAD 4  
#01-05/53 BARTLEY BIZ CENTRE  
SINGAPORE: ASIA MOTORSPORTS SOLUTION  
PTE LTD

Estimated Period of Repair: 3.0 days

**Adjuster:** MARCUS CHUA**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

|               |                                                                                                                                                                              |                                                        |
|---------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------|
| Reference     |                                                                                                                                                                              |                                                        |
| Part Source:  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 06 Mar 2022)          |
| Parts:        | 143                                                                                                                                                                          | TOYOTA CAMRY 2.0 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour:       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                      |
| Print Code:   | (Unsubmitted, no print-code for SMP7046J)                                                                                                                                    |                                                        |
| Validity:     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                        |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                        |

Recommended Parts

| No. | Qty | Part No. | Particulars                               | Condition       | Repairer's  | Amount       |
|-----|-----|----------|-------------------------------------------|-----------------|-------------|--------------|
| 1   | 1   |          | *REAR BUMPER ASSY (UPPER)                 | Dented/Deformed | 1,485.60 FL | *1,296.60 FL |
| 2   | 1   |          | *REAR BUMPER LOWER COVER (LOWER)          | Grazed          | 643.80 FL   | *450.10 FL   |
| 3   | 1   |          | *REAR BUMPER LEFT REFLECTOR               | Cracked         | 78.80 FL    | *68.10 FL    |
| 4   | 1   |          | *REAR BUMPER LEFT RETAINER                | Not Necessary   | 86.40 FL    | *- FL        |
| 5   | 1   |          | *REAR BUMPER LEFT BRACKET                 | Not Necessary   | 88.70 FL    | *- FL        |
| 6   | 1   |          | *REAR BUMPER REINFORCEMENT                | Repair          | 661.30 FL   | *- FL        |
| 7   | 1   |          | *REAR BUMPER SPONGE                       | Not fitted      | 155.80 FL   | *- FL        |
| 8   | 1   |          | *REAR BOOTLID ASSY                        | Not Necessary   | 1,652.90 FL | *- FL        |
| 9   | 1   |          | *REAR BOOTLID CENTRE LOGO                 | Not Necessary   | 78.80 FL    | *- FL        |
| 10  | 1   |          | *REAR BOOTLID CAMRY EMBLEM                | Not Necessary   | 76.40 FL    | *- FL        |
| 11  | 1   |          | *REAR BOOTLID HYBRID SYNERGY DRIVE EMBLEM | Not Necessary   | 75.80 FL    | *- FL        |
| 12  | 1   |          | *REAR BOOTLID LOCK MECHANISM              | Not Necessary   | 292.90 FL   | *- FL        |
| 13  | 1   |          | *REAR BOOTLID LOCK CATCH                  | Not Necessary   | 97.60 FL    | *- FL        |
| 14  | 1   |          | *REAR BOOTLID WEATHERSTRIP                | Not Necessary   | 288.10 FL   | *- FL        |
| 15  | 2   |          | *REAR BOOTLID HINGES                      | Not Necessary   | 225.50 FL   | *- FL        |
| 16  | 1   |          | *REAR BOOTLID INNER TRIM BOARD            | Not Necessary   | 403.90 FL   | *- FL        |
| 17  | 1   |          | *REAR BOOTLID OUTER GARNISH               | Not Necessary   | 192.60 FL   | *- FL        |
| 18  | 1   |          | *REAR BOOTLID RIGHT TAILLAMP              | Not Necessary   | 585.20 FL   | *- FL        |
| 19  | 1   |          | *REAR BOOTLID LEFT TAILLAMP               | Not Necessary   | 585.20 FL   | *- FL        |
| 20  | 1   |          | *REAR LEFT TAILLAMP                       | Scratched       | 992.30 FL   | *669.50 FL   |
| 21  | 1   |          | *REAR RIGHT TAILLAMP                      | Not Necessary   | 992.30 FL   | *- FL        |
| 22  | 1   |          | *REAR END LOWER PANEL                     | Repair          | 1,248.30 FL | *- FL        |
| 23  | 1   |          | *REAR END LOWER PANEL TOP GARNISH         | Not Necessary   | 324.60 FL   | *- FL        |
| 24  | 1   |          | *REAR LEFT FENDER ASSY                    | Not Necessary   | 1,645.90 FL | *- FL        |
| 25  | 1   |          | *REAR LEFT FENDER INNER COWLING           | Not Necessary   | 392.90 FL   | *- FL        |
| 26  | 1   |          | *REAR LEFT FENDER INNER GARNISH           | Not Necessary   | 425.10 FL   | *- FL        |
| 27  | 1   |          | *REAR WINDSCREEN GLASS MOULDING           | Not Necessary   | 188.80 FL   | *- FL        |
| 28  | 1   |          | *REAR EXHAUST MUFFLER ASSY                | Not Necessary   | 849.70 FL   | *- FL        |
| 29  | 2   |          | *REAR EXHAUST MUFFLER RUBBER MOUNTING     | Not Necessary   | 88.80 FL    | *- FL        |
| 30  | 1   |          | *REAR EXHAUST MUFFLER PIPE TIP            | Serviceable     | 285.30 FL   | *- FL        |
| 31  | 1   |          | *SET REAR BUMPER CLIPS                    | Necessary       | 60.00 FS    | *50.00 FS    |
| 32  | 4   |          | *REAR END LOWER PANEL TOP GARNISH CLIPS   | Not Necessary   | 30.00 FS    | *- FS        |
| 33  | 1   |          | *REAR END LOWER PANEL SEALANT             | Not Necessary   | 140.00 FS   | *- FS        |
| 34  | 2   |          | *REAR BUMPER REVERSE SENSOR               | Serviceable     | 300.00 FS   | *- FS        |
| 35  | 4   |          | *REAR BUMPER LOWER COVER CLIPS            | Not Necessary   | 30.00 FS    | *- FS        |
| 36  | 1   |          | *REAR NO PLATE WITH GARNISH               | Not Necessary   | 100.00 FS   | *- FS        |
| 37  | 1   |          | *REAR LEFT FENDER SEALANT                 | Not Necessary   | 100.00 FS   | *- FS        |
| 38  | 8   |          | *REAR LEFT FENDER INNER GARNISH CLIPS     | Not Necessary   | 40.00 FS    | *- FS        |
| 39  | 6   |          | *REAR LEFT FENDER INNER COWLING CLIPS     | Not Necessary   | 40.00 FS    | *- FS        |
| 40  | 1   |          | *REAR WINDSCREEN GLASS SEALANT            | Not Necessary   | 100.00 FS   | *- FS        |
| 41  | 4   |          | *REAR BOOTLID OUTER GARNISH CLIPS         | Not Necessary   | 30.00 FS    | *- FS        |
| 42  | 10  |          | *REAR BOOTLID INNER TRIM BOARD CLIPS      | Not Necessary   | 50.00 FS    | *- FS        |
| 43  | 1   |          | *REAR VIEW CAMERA                         | Not Necessary   | 450.00 FS   | *- FS        |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                     |           |          |
|-----------------------------------------------------|-----------|----------|
| Sub Total (\$\$)                                    | 16,659.30 | 2,534.30 |
| - List Item Discount on L Items 25.00/25.00% (\$\$) | 3,797.33  | 621.08   |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars | Condition | Repairer's               | Amount           |
|-----|-----|----------|-------------|-----------|--------------------------|------------------|
|     |     |          |             |           | <b>Total Parts (S\$)</b> | <b>12,861.97</b> |
|     |     |          |             |           |                          | <b>1,913.22</b>  |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                            | Particulars                                                                                    | Lab.Type | Repairer's      | Amount          |
|-------------------------------|------------------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>           |                                                                                                |          |                 |                 |
| 1                             | LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN REAR AFFECTED AREA AND REPLACE REAR DAMAGED PARTS | New      | 1,200.00        | 500.00          |
| 2                             | TO PUTTY AND SPRAY PAINTING REAR PORTION                                                       | New      | 1,200.00        | 600.00          |
| 3                             | TO CHECK REAR LIGHTING AND WIRING                                                              | New      | 50.00           | 20.00           |
| 4                             | TO REMOVE AND INSTALL REAR BOOTLID LOCK MECHANISM                                              | New      | 80.00           | 0.00            |
| 5                             | TO REMOVE AND INSTALL REAR EXHAUST MUFFLER ASSY                                                | New      | 120.00          | 0.00            |
| 6                             | TO REMOVE AND INSTALL REAR FUEL TANK TO FACILITATE THE REPAIR                                  | New      | 180.00          | 0.00            |
| 7                             | TO REMOVE AND INSTALL REAR INNER GARNISH AND TRIM TO FACILITATE THE REPAIR                     | New      | 140.00          | 80.00           |
| 8                             | TO APPLY ANTI RUST PROOFING TO REAR AFFECTED AREA                                              | New      | 140.00          | 0.00            |
| 9                             | TO REMOVE AND INSTALL REAR BUMPER REVERSE SENSOR                                               | New      | 80.00           | 50.00           |
| 10                            | TO REMOVE AND INSTALL REAR WINDSCREEN GLASS TO FACILITATE THE REPAIR                           | New      | 140.00          | 0.00            |
| 11                            | TO REMOVE AND INSTALL REAR VIEW CAMERA                                                         | New      | 80.00           | 0.00            |
| 12                            | TOWING SERVICE                                                                                 | New      | 100.00          | 0.00            |
| <b>Gross Labour Cost (\$)</b> |                                                                                                |          | <b>3,510.00</b> | <b>1,250.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >