

ASS. REC. BY:

REF:

ICS/22000731/K4

Kenneth

CS/ICS22000731/K4f3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

MPC21P00264400

Claims No.

DMPC2200010H

Sum Insured:

Excess:

3500

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

853K

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

09

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMP8584R Yr Regn: 12, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Citroen 4 Cactus

c.c

1199

Colour

Red

A/C:

Insured / Std / NI / NA

Sp. Reading

74681

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VF70PHN8W14E538501

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / 8/Rim / STD A/Rim or

Tyre Size:

F:

215/50R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

8

mm

L/Bal.

7

mm

L/Bal.

8

mm

D.O.A.

9/1/22

D.O.I.

20/1/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

LUMP SUM \$4500,9DAYS

RED:22,390.00;83%

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

9

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

Not Authorized
61 Png &
Penny After Png
9 days
Et B350d

LIBERTY INSURANCE PTE LTD

51 CLUB STREET

LIBERTY HOUSE

SINGAPORE 069428

ATTN: ACCIDENT CLAIMS DEPARTMENT

ESTIMATE

DATE :

VEHICLE NO :

VEH MAKE/MODEL :

YOM :

CHASSIS NO :

DATE OF ACCIDENT :

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

NO	QTY	DESCRIPTION	LIST PRICE:-	AMOUNTS
1	1	REAR TAIL GATE	rx	X
2	1	REAR TAIL GATE LOCK	rx	X
3	1	REAR TAIL GATE LOGO	rx	X
4	1	REAR TAIL GATE LOGO "C4"	rx	X
5	1	REAR TAIL GATE LOGO "CACTUS"	rx	X
6	1	REAR TAILGATE CENTRE PANEL	rx	X
7	1	REAR TAIL GATE INNER TRIM BOARD	rx	X
8	1	REAR LAMP LH	rx	X
9	1	REAR LAMP LOWER BRACKET LH	rx	X
10	1	REAR LAMP RH	rx	X
11	1	REAR LAMP LOWER BRACKET RH	rx	X
12	1	REAR BUMPER	Bu ✓ + Bumper Tow Cover	
13	2	REAR BUMPER SIDE RETAINER	+ Reverse Sensor (if original)	
14	1	REAR BUMPER LOWER	Reverse Sensor Seal	
15	1	REAR BUMPER CENTRE LOWER (?)		
16	✓	REAR CORNER GARNISH PANEL LH * BELOW TAILGATE	Lamp	rx
17	✓	REAR CORNER GARNISH PANEL RH * BELOW TAILGATE	Lamp	rx
18	1	REAR REFLECTOR LH	rx	
19	1	REAR REFLECTOR RH	rx	
20	1	REAR WEATHERDHIELD	rx	
21	1	REAR END PANEL	Bu ✓	
22	1	REAR END PANEL GARNISH	rx	
23	SET	REAR TAIL GATE GLASS MOULDING	rx	
24	1	REAR FENDER LH	rx	
25	1	REAR FENDER SHIELD LH	rx	
26	1	REAR FENDER WHEEL ARCH LH	Bu rx	
27	1	REAR FENDER RH	rx	
28	1	REAR FENDER SIELD RH	rx	
29	1	REAR FENDER WHEEL ARCH RH	Bu ✓	
30	✓	FRONT HEADLAMP LH + Headlamp Garnish	?	
31	1	FRONT HEADLAMP LOWER BRACKET LH	?	
TOTAL - LIST ITEM			\$	-
LIST 20%			\$	-

Acknowledged by Repairer

Signature:

Date:

rx

TOTAL

\$

Page 1/3

32	1	FRONT HEADLAMP RH	Handlamp	Garnish	7
33	1	FRONT HEADLAMP LOWER BRACKET RH			7
34	1	FRONT BUMPER		Rx	
35	2	FRONT BUMPER SIDE RETAINER LH & RH		Rx	
36	1	FRONT BUMPER LOWER COVER	+ Front Bumper Lower	Rx	
37	1	FRONT GRILLE TOP	Centre	Rx	
38	1	FRONT GRILLE CHROME			
39	1	FRONT GRILLE LOWER			
40	1	FRONT EMBLEM			
41	1	FRONT FOGLAMP LH		Rx	
42	1	FRONT FOGLAMP GARNISH LH			
43	1	FRONT FOGLAMP RH		Rx	
44	1	FRONT FOGLAMP GARNISH RH		Rx	
45	1	FRONT SIGNAL LAMP LH *BUMPER		Rx	
46	1	FRONT SIGNAL LAMP RH *BUMPER		Rx	
47	1	FRONT REINFORCEMENT		Rx	
48	2	FRONT REINFORCEMENT ARM		Rx	
49	1	FRONT SUPPORT PANEL			
50	1	FRONT NUMBER PLATE GARNISH	(* Centre in Centre Grille?)	7	
51					
52					
53					
54					
55					

TOTAL - LIST ITEM

\$

-

LIST

20%

\$

-

TOTAL

\$

-

Page 2/3

SPECIAL NETT ITEMS:-

1	1	REVERSE SENSOR (if original Sensor put into List)	\$	Phon	360.00
2	SET	REAR BUMPER CLIPS & REAR FENDER SHIELD CLIPS	\$	Rx	60.00
3	2 SET	REAR END PANEL GARNISH CLIPS	\$	Rx	45.00
4	SET	REAR TAILGATE GLASS SEALANT	\$	Rx	80.00
5	SET	REAR FENDER WHEEL ARCH CLIPS LH & RH	\$	c/s Rx	80.00
6	SET	REAR NUMBER PLATE WITH FRAME	\$	Rx	50.00
7	SET	FRONT BUMPER & FRONT FENDER SHIELD CLIPS	\$	Rx	60.00
8	SET	FRONT NUMBER PLATE WITH FRAME	\$	Rx	50.00

2001A

✓

X

X

LX

450A

X

450A

[illegible]

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 10/01/2022 11:47 (SGT)
Date of Accident 09/01/2022 15:40 (SGT)
Exact Location of Accident PIE, Singapore
Additional Location Information Along PIE (Changi Airport) Before Upper Serangoon Exit
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMP8584R

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner Muhammad Syirazi Bin Charman
NRIC No SXXXX002E
Email Address Syirazl_charman@ymail.com
Mobile Phone No (Phone) +65-87210890
Alternative Phone No +65-87210891

VEHICLE PARTICULARS

Manufacturer Citroen
Model C4 Cactus
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? Yes
Vehicle Category Private car
Transmission Auto
CC 1200


INSURANCE COMPANY

Name of Insurance Company ECICS Limited
Type of Coverage Comprehensive
Fleet Policy No
Policy Number MPC21P00264400
Cover Note Number -

DRIVER

Name of Driver Farah Ummaina Binte Adnan
NRIC No SXXXX973J

Sketch Plan



PIE (Changi Airport) before upper Serangoon Rd Exit

Describe Circumstances of the Accident

Location: Along PIE (Changi Airport) Before upper Serangoon Rd Exit
 Date of Accident: 9/1/22 Time of Accident: 1st hrs
 Vehicle A: SM73562 Vehicle B: SMN 58662 Vehicle C: SM73562

There was another collision right in front of our accident.
 The car in front of me was constantly braking and I kept my distance.
 The moment he (veh C) brake abruptly, I brake as well, leaving sufficient space between me and him (veh C). However, the car behind me couldn't stop in time and hit the rear of my car.

Declaration

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature / Date & Time


 Driver's Signature (If driver is not the policyholder) / Date & Time


 Witnessed by Reporting Centre Personnel

10 JAN 2022