

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MPC21P00264400	Date of Loss:	09/01/2022
Vehicle Reg. No.:	SMP8584R	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	MUHAMMAD SYIRAZI BIN CHARMAN		
Driver:	FARAH UMMAINA BINTE ADNAN		
Make/Model:	CITROEN C4 CACTUS, 1.2 AT6 (A)	Vehicle Reg. Date:	27/12/2017
Vehicle Colour:	BLACK		
Engine No:	10XVA10741542	Chassis No:	VF70PHNZWHE538501
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	8		
Present Location:	ACCORD AUTO SERVICES PTE LTD (HQ)		

*Not whitened
11Lm @ 4500p
Showering After Paint
9 days
4x @ 3500p*

COST OF CLAIMS	Amount
Parts	22,055.00
Miscellaneous Items	785.00
Labour	4,050.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	26,890.00
+ GST 7.00% (S\$)	1,882.30
Nett Amount (S\$)	28,772.30

This claim is handled by: GOH JACQUELINE

City & County
 After Point
 9 days

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 20 Jan 2022)
 Parts: N/A CITROEN C4 CACTUS 1.2 AT6 (A) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SMP8584R)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*REAR TAIL GATE	R	0.00	0.00	*800.00 F X
2	1		*REAR TAIL GATE LOCK	R	0.00	0.00	*200.00 F X
3	1		*REAR TAIL GATE LOGO	nn	0.00	0.00	*80.00 F X
4	1		*REAR TAIL GATE LOGO C4	nn	0.00	0.00	*60.00 F X
5	1		*REAR TAIL GATE LOGO CACTUS	nn	0.00	0.00	*60.00 F X
6	1		*REAR TAILGATE CENTRE PANEL	Sn	0.00	0.00	*460.00 F X
7	1		*REAR TAIL GATE INNER TRIM BOARD	Sn	0.00	0.00	*350.00 F X
8	1		*REAR LAMP LH	Sn	0.00	0.00	*600.00 F X
9	1		*REAR LAMP RH	Sn	0.00	0.00	*600.00 F X
10	1		*REAR BUMPER	Rn	0.00	0.00	*120.00 F ✓
11	1		*REAR BUMPER SIDE RETAINER LH & RH	Sn	0.00	0.00	*160.00 F X
12	1		*REAR BUMPER LOWER	At/low	0.00	0.00	*350.00 F ✓
13	1		*REAR BUMPER CENTRE LOWER	Rn	0.00	0.00	*320.00 F ✓
14	1		*REAR BUMPER TOW COVER	Sn	0.00	0.00	*400.00 F X
15	1		*REAR CORNER GARNISH PANEL LH * BELOW LAMP	Sn	0.00	0.00	*400.00 F X
16	1		*REAR CORNER GARNISH PANEL RH * BELOW LAMP	Sn	0.00	0.00	*400.00 F X
17	1		*REAR REFLECTOR LH	Sn	0.00	0.00	*250.00 F X
18	1		*REAR REFLECTOR RH	Sn	0.00	0.00	*250.00 F X
19	1		*REAR WEATHERSHIELD	SVC	0.00	0.00	*260.00 F ✓
20	1		*REAR END PANEL	Rn	0.00	0.00	*400.00 F ✓
21	1		*REAR END PANEL GARNISH	Sn	0.00	0.00	*100.00 F X
22	1		*REAR TAIL GATE GLASS MOULDING		0.00	Svc 0.00	-
23	1		*REAR FENDER LH	R	0.00	0.00	*2,000.00 F X
24	1		*REAR FENDER SHIELD LH	Sn	0.00	0.00	*100.00 F X
25	1		*REAR FENDER WHEEL ARCH LH	Sn	0.00	0.00	*290.00 F X
26	1		*REAR FENDER RH	R	0.00	0.00	*2,000.00 F X
27	1		*REAR FENDER SHIELD RH	Sn	0.00	0.00	*100.00 F X
28	1		*REAR FENDER WHEEL ARCH RH	Rn	0.00	0.00	*290.00 F ✓
29	1		*FRONT HEADLAMP LH	Sn	0.00	0.00	*800.00 F X
30	1		*FRONT HEADLAMP LOWER BRACKET LH	Sn	0.00	0.00	*180.00 F X
31	1		*FRONT HEADLAMP GARNISH LH	SVC	0.00	0.00	*150.00 F X
32	1		*FRONT HEADLAMP RH	Sn	0.00	0.00	*800.00 F X
33	1		*FRONT HEADLAMP LOWER BRACKET RH	R	0.00	0.00	*180.00 F X
34	1		*FRONT HEADLAMP GARNISH RH	Sn	0.00	0.00	*150.00 F X
35	1		*FRONT BUMPER	Rn	0.00	0.00	*1,200.00 F ✓
36	1		*FRONT BUMPER SIDE RETAINER LH & RH	Sn	0.00	0.00	*240.00 F X
37	1		*FRONT BUMPER LOWER	At/low	0.00	0.00	*350.00 F ✓
38	1		*FRONT GRILLE CENTRE	Sn	0.00	0.00	*650.00 F X
39	1		*FRONT EMBLEM	Rn	0.00	0.00	*140.00 F ✓
40	1		*FRONT FOGLAMP LH	Sn	0.00	0.00	*280.00 F X
41	1		*FRONT FOGLAMP GARNISH LH	Sn	0.00	0.00	*150.00 F X
42	1		*FRONT FOGLAMP RH	Sn	0.00	0.00	*280.00 F X
43	1		*FRONT FOGLAMP GARNISH RH	Sn	0.00	0.00	*150.00 F X
44	1		*FRONT SIGNAL LAMP LH *BUMPER	Sn	0.00	0.00	*550.00 F X
45	1		*FRONT SIGNAL LAMP RH *BUMPER	Sn	0.00	0.00	*550.00 F X

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
46	1		*FRONT REINFORCEMER ARM LH & RH	0.00	0.00	*360.00 F X12
47	1		*FRONT NUMBER PLATE GARNISH	0.00	0.00	*280.00 F ?
48	1		*REVERSE SENSOR SET	0.00	0.00	*480.00 F X
49	1		*REVERSE SENSOR SEAL SET	0.00	0.00	*180.00 F
50	1		*FRONT SUPPORT PANEL	0.00	0.00	*550.00 F X
51	1		*FRONT BUMPER TOW COVER	0.00	0.00	*-F ?

} serviceable Repeat.

F=Franchise part.

Sub Total (\$\$)	20,050.00
+ Margin on L,N Items 10.00% (\$\$)	2,005.00
Total Parts (\$\$)	22,055.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

Qty	Particulars	Amount
Miscellaneous Items		
1	FRONT BUMPER & FRONT FENDER SHIELD CLIPS	na 60.00 X
1	FRONT NUMBER PLATE WITH FRAME	na 50.00 45.00
1	REAR BUMPER CLIPS & REAR FENDER SHIELD CLIPS	na 60.00 X
1	REAR END PANEL GARNISH CLIPS	na 45.00 X
1	REAR FENDER WHEEL ARCH CLIPS LH & RH	ol/na 80.00 45.00
1	REAR NUMBER PLATE WITH FRAME	na 50.00 X
1	REAR TAILGATE GLASS SEALANT	na 80.00 X
1	REVERSE SENSOR SET	short 360.00 260.00
Sub Total (S\$)		785.00

Estimates on Labour

Particulars	Lab.Type	Amount
Labour Items		
SPRAY PAINT ON ALL AFFECTED AREA (FRONT & REAR)	New	1,200.00 800
LABOUR REMOVE/REFIX ACCIDENT DAMAGE PARTS TO KNOCK, JACK, CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	New	1,500.00 1200
TO CHECK WIRING SYSTEM & LIGHT	New	100.00 40
TO APPLY ANTI RUST TREATMENT	New	na 120.00 X
TO REMOVE/REFIX REVERSE SENSOR	New	150.00 50
TO REMOVE/REFIX REAR INNER COMPARTMENT TO FACILITIES REPAIR	New	na 150.00 X
TO REMOVE/REFIX REAR TAILGATE, TOP SPOILER, WIPER MOTOR, MECHMISM & ETC TO NEW TAILGATE	New	na 300.00 X
TO CHECK WATER LEAKING	New	150.00 20
COMPUTER DIAGNOSTIS AFTER REPAIR	New	na 380.00 X
Gross Labour Cost (S\$)		4,050.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: