

ASS. REC. BY: *MACUS*

REF:

*CC6/A1622000734/Ueq3***ASSIGNMENT**

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$ )

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

c.c

Colour

A/C:

Sp. Reading

T/Radio:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: N / S / Rim / STD A / Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Add Fee:

☐

Site Insp (\$ )

☐

Interview (\$ )

☐

Tech. Invs (\$ )

☐

Weekend (\$ )

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

FASTECH AUTO PTE LTD  
1 Kaki Bukit Ave 6 #01-48 Autobay  
Singapore 417883  
Tel No: 67452063/ 67467158 Fax No: 67458520  
Tax Reg No : 200006262D

not Approved  
hbc  
20/1/22  
4/5 \$3500  
Hdngs

VEHICLE No: GBE 6361T

list ITEM

|      |                                                        |            |                     |             |             |
|------|--------------------------------------------------------|------------|---------------------|-------------|-------------|
| 1PC  | REAR TAILGATE                                          | 20/Seat    | 1482.50             | \$2,660.00  | ✓           |
| 2PCS | REAR TAILGATE LOCK LATCHES @\$380.00                   | R          |                     | \$760.00    | X           |
| 2PCS | REAR TAILGATE LOCK LOWER 'L' BRACKETS @\$180.00        | N/S 3 each | 110.50              | \$360.00    | 1PC         |
| 2PCS | REAR TAILGATE LOCK LOWER 'L' BRACKER RUBBERS @\$120.00 | each       |                     | \$240.00    | X           |
| 1PC  | REAR TAILGATE 'DYNA' STICKER                           | Nu         | 28.60               | \$80.00     | ✓           |
| 2PCS | TAILLAMPS @\$450.00                                    | each       | 295.10 x 2 = 590.20 | \$900.00    | ✓           |
| 2PCS | TAILLAMP HOUSING PANELS @\$180.00                      | R          |                     | \$360.00    | X           |
| 1PC  | REAR LICENCE PLATE BRACKET                             | Seat       | 184.20              | \$345.00    | ✓           |
| 1PC  | REAR EXHAUST                                           | 11         |                     | \$1,250.00  | X           |
| 1PC  | REAR EXHAUST MOUNTING                                  | 11         |                     | \$85.00     | X           |
| 1PC  | REAR TAILGATE LOWER PANEL                              | 20/Seat    | 580.40              | \$840.00    | ✓           |
| 1PC  | REAR SPARE TYRE CARRIER & CHAIN                        | 11         |                     | \$680.00    | X           |
| 1PC  | DROPSIDE GATE PANEL N/S                                | R          |                     | \$2,890.00  | X           |
| 1PC  | DROPSIDE GATE PANEL O/S                                | Nu         |                     | \$2,890.00  | X           |
|      |                                                        |            |                     | \$14,340.00 |             |
|      |                                                        |            |                     | LESS 10%    | \$12,906.00 |

S.NETT

|      |                                       |        |            |     |
|------|---------------------------------------|--------|------------|-----|
| 1SET | REAR TAILGATE '70km/h & 12pax STICKER | Nu     | \$50.00    | 20  |
| 1SET | REAR REVERSE SENSOR                   | Shovel | \$300.00   | 200 |
| 1PC  | REAR LICENCE PLATE                    | CRS    | \$50.00    | 40  |
| 1SET | REAR CARGO DECK STOPPER RUBBER        | 11     | \$200.00   | X   |
| 2PCS | REAR REFLECTORS @\$115.00             | CRS    | \$230.00   | 150 |
| 1PC  | REAR STEP BRACKET                     | Seat   | \$300.00   | 180 |
|      |                                       |        | \$1,130.00 |     |

|                                           |             |     |
|-------------------------------------------|-------------|-----|
| TO CHECK WIRING                           | \$50.00     | 20  |
| TO DISMANTLE & REPLACED REVERSE SENSOR    | \$100.00    | 50  |
| TO DISMANTLE & REPLACED REAR CARGO DECK   | \$800.00    | X   |
| TO STRAIGHTEN & REALIGN CHASSIS           | \$1,000.00  | X   |
| TO SPRAY RUST PROOFING                    | \$200.00    | 60  |
| LABOUR FOR PANEL BEATING & REPLACED PARTS | \$1,500.00  | 680 |
| TO PUTTY & SPRAY PAINTING                 | \$1,800.00  | 750 |
| TOTAL                                     | \$19,486.00 |     |

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before and after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party's view is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

MO:

P-3006.60  
252  
P-2254.95  
S.N-590.00  
L-1860  
4404.55