



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBS 21R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	SPRAY PAINT - GREEN;600ML;SG BUS.	NOT NECESSARY	30.00	-
	CONTRACTOR LABOUR COST.	NOT CONSISTENT WITH THE IMPACT	550.00	-
	WORKSHOP ASSESSMENT LABOUR COST.	NOT NECESSARY	192.00	-
	LIVERY / ADVERTISEMENT COST. (NPA)	NOT NECESSARY	-	-
	TOWING COST. (NPA)	NOT NECESSARY	-	-
			772.00	-
	GRAND TOTAL		772.00	-
	RECOMMENDED COST OF REPAIRS			-

Report Ref No. CS1/LPC22000736/Etf3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.