

AUTOTEAM ENGINEERING PTE LTD

7 Gambas Crescent #04-07 Singapore 757087

Tel: (65) 6253 0233 Email: sales@autoteam.com.sg

Co. Reg. No. 201205841K



QUOTATION

Quote To

SBS Transit Ltd

Seletar Workshop

3 Yio Chu Kang Crescent

Singapore 786010

Quotation No. Q22010097

Date 19 Jan 2022

Terms Net 30

Attn: Mr Nurizman

S/No	Description	ManHour	ManHour Rate	Amount
<u>Repair Accident Bus - SBS 21R</u>				
1.	Supply workers for 11 ManHours	11	S\$50.00	S\$550.00
-	Repair Right Side Front Dome			
-	Repair Interior Front Windscreen Shield			
-	Spray Painting Right Side Front Dome			
-	Spray Painting Interior Front Windscreen Shield			



Remark(s) All Material To Be Supplied by SBST

Total S\$550.00

This is computer generated. No signature is required.

NURIZMAN BIN YUSOFF
TECHNICAL OFFICER
SELETAR BUS WORKSHOP

20 JAN 2022

RERPORT-ID : TAC019R
USER-ID : edsfof02

ACCIDENT REPORT

DATE : 12/01/2022 15:36:54
Page : 1 of 2

12315 - AMI

Company	SBS	District	SE	IP NUMBER	
Duty IO	ANG CHONG BOON	Report No.	E/0192/2022	Accident Date	12/01/2022
Report Date	12/01/2022	Shift Code	AM SHIFT	Accident Time	13:20
Place of Accident	BALESTIER ROAD BUS STOP (50239, 7.4 KM)				
Road Name	BALESTIER ROAD	Road Name			
		Junction			
		Final Cause			
Accident Type	TRAFFIC	Nature Of Accident	MINOR		
Weather Code	CLEAR	Road Surface	DRY		
Operating Hours	WORKED 8 HRS	Type Of Location	BUS STOP		
Traffic Volume	MODERATE	Traffic Flow	TWO WAYS		
Traffic Control	UNCONTROLLED	Ambulance Convey	N		
Collision With	VEHICLE	Type Of Collision	SIDE SWIPE - SAME DIRECTION		
Fatal	0	Serious Injury	0	Minor Injury	0
Police Report	N	Police Report Number		Photo Taken	Y
Bus Towed	N	Sketch	Y	Mechanical Fault	N
Urgent CBR Status	N	CFMS Case	N	CFMS No	
Damage To Bus	SBS21R - RIGHT FRONT DMG ?				
Facts of Incident	I stopped at the bus stop (50239, 7.4 KM) yellow box along Balestier road when a trailer (XB3954H) 's left rear side swipe the right front of my bus. The latter was entering my lane when the accident occurred. No injury. That 's all.				
Brief Particulars	NA				
Reason for Late Report					

STATEMENT READ OVER TO ME _____
AND I AFFIRM IT TO BE TRUE AND CORRECT

THAM MENG KHUAN
Safety Officer
Selatut Depot

SIGNATURE OF STAFF

NAME AND DESIGNATION OF RECORDER

3P