

Date:

		XIN YUN AUTO PTE LTD BLK8 #05-23 Premier, Kaki Bukit Ave4 (415875)				
	1	Sale not be remain, take parties (1235/5)				
RECON	AMEN	DED PARTS		Vehicle No.:	XD4937R	
No.			Condition	Repairer	Adjuste	4
1	1	Safe stop TMA Truck Mounted Attenuators		70,000.00		
				48,0	00	
			Sub Total (S\$) :		-	
			Total Parts (S\$):	70,000.00		-
		DED SPECIAL NETT ITEMS				
No.	Qty 1	Part No. Descriptions Supply of metal bracket for the TMA installation	Condition	Repairer	Adjuste:	
2	2			1,500.00 >	/	
3		Flashing arrow led light board for both side		1,200.00 >	A	
	1	Xenon strobe light on top		600.00 >		
4	1	Danger keep clear -yellow green type with sign panel		800.00		
5	1	Yellow green type wide angel prismatic sticker "Split C		900:00		
6	1	Yellow green type wide angle prismatic sticker with tro	uck number	600.00		
7	1	Customized TMA ID plate		400.00	×	_
			Sub Total (S\$):	6,000.00	-	-
RECON	MEN	DED LABOUR				
No.		Descriptions		Repairer	Adjuste	
		LABOUR ITEMS				
1		TO dismantle and install new TMA, focus on damaged portin, pa	inel beating and	5,000.00	1200	
		reshaper, straighten, orientate and align the whole repair		-		
2		To do the alignment, after the TMA installation		300.00	4	
3		To do all the led woring light setting up work and check wiring		1,000.00	60	
4		To install the yellow green type sign panel		500.00	X	
5		Remove exiting TMA, remove the old type of frame and old type	e TMA support	2,000.00	X	
6		Remove and install all new set of sticker		800.00	tou	
7		Install TMA ID Plate		300.00		
		PAINTWORK LABOUR				
7		Supply spray material to TMA and rear damaged portion		3,000.00 7	2	
					1	_
			Total Labour (S\$):	12,900.00	-	=
COST C	F CLA	MS		Repairer	Adjusted	
1		PARTS		70,000.00	-	- Vasul
2		SPECIAL NETT ITEMS		6,000.00	-	
3		LABOUR		9,900.00		11 Simin LV
4		PAINTWORK LABOUR		3,000.00	-	Hp 2001068
			Gross Total (S\$):	88 900 00		5 days
			GST 7.00% (S\$):	30,300.00		
		LKK Auto Consultants hence notify		99 000 00		OP'
		the Repairer of the following:	Total Amount (S\$):	00,300.00	-	
		To resurvey before/after spray painting				1
		 To display damaged part(s) during resurvey 				22/01/22/01/11
		 Parts prices are subject to confirmation 				210112
		• Third party survey is on a "Without Projection" by				ticke-rel
Confiden	itial and	No illegal modification(s) is allowed basis No illegal modification(s) is allowed basis Supplementary item(s) must be resurveyed and including the supplementary item(s) must be resurveyed and item supplementary item(s) must be resurveyed and item supplementary item supplement				txus. In
		Supplementary item(s) must be resurveyed and				Qualos
		is subject to final approval from Insurance Company				thouse
		Acknowledged by Repairer		0	0	Exces: TBA PENTER after reprier
		Signature:			Las	a fav my
		Date:				,