



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:CHAN KIAN CHUAN			Ref: CC4/ASM22000745/Aea3q2 Date: 18/05/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHC 2348Z	Veh. Inspected	SJX 9971T
	Policy No.	P2465679	Coverage (\$)	0.00
	Claim No.	S2M03RH4	Excess (\$)	0.00
	Assign From		Assign Date	20/01/2022
2. Vehicle Particulars & Condition				
	Make & Model	SUBARU FORESTER	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	JF1SJGK85HG093268	Colour	GREY
	Odometer	156910 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/55 R18	PIRELLI	6 mm
	L/H Front Tyre	235/55 R18	PIRELLI	6 mm
	R/H Rear Tyre	235/55 R18	PIRELLI	6 mm
	L/H Rear Tyre	235/55 R18	PIRELLI	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	19/01/2022	Inspection Date	20/01/2022
	Survey held at	SM AUTOMOTIVE BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days