

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged parts during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

NEW ZEN WERKZ PTE LTD

BLK 3 KAKI BUKIT RD 1 #03-04 EUNOS TECHNOLINK SINGAPORE 415935

FARISHA BTE MOHD SIKANDAR

Blk 3 Kaki Bukit Road 1

03 – 04 Eunost Technolink

Singapore 415935

20th Jan 2022

Accident date: 17th Jan 2022

Estimated repair cost for vehicle no: SJV5082X MITSUBISHI LANCER

S/n	Qty	Items/Nett	U/price	Amount
1	1	Front headlamp -RH <i>lt</i>		\$852.00 ✓
2	1	Front bumper <i>Distorted</i>		1500 1000(SN) ✓
3	2	Front Bumper Side Bracket <i>Here</i>	\$112.00	\$224.00 X
4	2	Front Bumper Side retainer <i>RH Bnd</i>	\$125.00	250.00 45 ✓
5	1	Front bumper number plate		\$50.00 X
6	1	Front bumper number plate garnish		\$32.00 X
7	1	Front bumper center lower garnish <i>Here</i>		\$145.00 X
8	1	Front bumper fog lamp-RH <i>Cushed</i>		\$215.00 ✓
9	1	Front bumper fog lamp cover -RH <i>Here</i>		\$113.00 X
10	6	Front bumper clips <i>New</i>	\$8.00	\$48.00 ✓
11	1	Front grille <i>Here</i>		\$325.00 X
12	1	Front grille emble logo <i>Here</i>		\$35.00 X
13	1	water tank		\$258.00 X
14	1	Front R/H fender <i>Here</i>		\$541.00 X
15	1	Front R/H fender cowling <i>Torn</i>		\$107.00 ✓
16	8	Front R/H fender cowling clips <i>Here</i>	\$5.00	\$40.00 ✓

Subtotal :- \$3,943.00

Labour charges

To remove & re-fix cushion

\$120.00 X

To Check Wiring System

\$60.00 30

To remove & re-fix front RH undercarriage

\$0.00 X

Wheel alignment (computer)

\$120.00 X

Towing charges

\$80.00 X

Tuff kote

\$150.00 X

Panel beating

\$800.00 200

Spray painting

\$800.00 250

Subtotal :- \$2,130.00

Total:- \$6,073.00