



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897			Ref: CS/AIS22000751/Aqf3e2	
			Date: 29/03/2022	
			Code: AIS	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	YN 2463P	Veh. Inspected	SLJ 9426B	
Policy No.	SPMF1000000448	Coverage (\$)	0.00	
Claim No.	AURASCL2022-00015FR	Excess (\$)	0.00	
Assign From	SHANTI	Assign Date	21/01/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA WISH	c.c	1794	
Engine No.	HIDDEN	Year of Reg.	2006	
Chassis No.	ZNE100296457	Colour	SILVER	
Odometer	221156 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/45 R17	FIRENZA	6 mm	
L/H Front Tyre	225/45 R17	FIRENZA	6 mm	
R/H Rear Tyre	225/45 R17	FIRENZA	6 mm	
L/H Rear Tyre	225/45 R17	FIRENZA	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	20/01/2022	Inspection Date	21/01/2022	
Survey held at	YSK AUTO WORKSHOP 1 KAKI BUKIT AVE 6 @ AUTOBAY #01-71 SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	