

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/OD/0048/2022/JT  
**DATE** : 19-Jan-22  
**WIP** : 64158

**VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 20/1/22**

**AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

**Tel: 6880 4602 - Fax: 6880 4838**

**Hi Adrian**

**7 days exclude 1 Sunday**

**Johnny Boo 14 Mar 22**

**OWNER'S NAME** : ME LEONG XIANRONG TIMOTHY  
**ADDRESS** : 13 MOUNT SOPHIA  
#04-42  
SINGAPORE 228471  
**TELEPHONE** : HP +65 91724599  
**TYPE OF CLAIM** : OWN DAMAGE CLAIM  
**POLICY NO** : 7210067109  
**VEHICLE NO** : **SBY 2222 H**  
**MODEL CODE** : AUDI A4 2.0 TFSI TRONIC  
**MODEL YEAR** : 30/6/2021  
**ENGINE NO** : DEM 027403  
**CHASSIS NO** : WAUZZZF48MN004590  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 19-Jan-22  
**PLACE OF ACCIDENT** : JUNCTION OF BUKIT TIMAH ROAD  
AND CLUNY PARK ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

### ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SBY 2222 H

| S/N                         | NATURE OF JOBS                                                                                                                                                                                               |        | ESTIMATED<br>CHARGES |           | SURVEYOR'S<br>RECOMMENDATIONS |
|-----------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|----------------------|-----------|-------------------------------|
| 1                           | TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.                                                             | S/N \$ | 480.00               | \$        | <b>480.00</b>                 |
| 2                           | TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.                                                                                                                                       | S/N \$ | 700.00               | \$        | <b>250.00</b>                 |
| 3                           | TO REMOVE AND RENEW AIRCON CONDENSER, CHANGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM, VACUUM AND REGAS.                                                   | S/N \$ | 1,900.00             | \$        | <b>980.00</b>                 |
| 4                           | TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDERS AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. | \$     | 5,600.00             | \$        | <b>1,000.00</b>               |
| 5                           | TO RESPRAY FRONT BUMPER, BONNET, HINGES AND BOTH FRONT FENDER.                                                                                                                                               | \$     | 4,000.00             | \$        | <b>1,100.00</b>               |
| 6                           | <b>Add labour</b>                                                                                                                                                                                            | \$     | <b>780.00</b>        | \$        | <b>780.00</b>                 |
| 7                           | TO CARRY OUT DIAGNOSTIC CHECK.                                                                                                                                                                               | S/N \$ | 192.00               | \$        | <b>192.00</b>                 |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                                                                              | :      | <b>\$ 13,652.00</b>  | <b>\$</b> | <b>4,782.00</b>               |

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SBY 2222 H**

|                              |                                             |     | DAMAGED PARTS & PRICES |           |                 |
|------------------------------|---------------------------------------------|-----|------------------------|-----------|-----------------|
| S/N                          | PARTS DESCRIPTION                           | QTY | S/NETT                 | REMARKS   |                 |
| 1                            | FRONT BUMPER                                | 1   | \$ 2,377.00            | \$        | 1,901.60        |
| 2                            | FRONT BUMPER FIXING PARTS                   | 1   | \$ 393.00              |           |                 |
| 3                            | FRONT BUMPER SECURING STRIP                 | 2   | \$ 79.00               |           |                 |
| 4                            | FRONT BUMPER GRILLE - CENTER                | 1   | \$ 219.00              | \$        | 174.80          |
| 5                            | FRONT BUMPER CLOSING ELEMENT - LOWER CENTER | 1   | \$ 293.00              | \$        | 234.00          |
| 6                            | FRONT BUMPER AIR GUIDE - LH / RH            | 2   | \$ 102.00              |           |                 |
| 7                            | FRONT BUMPER CLOSING ELEMENT - UPPER CENTER | 1   | \$ 293.00              |           |                 |
| 8                            | FRONT BUMPER AIR GUIDE GRILLE - LH / RH     | 2   | \$ 302.00              | \$        | 120.40          |
| 9                            | FRONT BUMPER AIR GRILLETRIM - LH / RH       | 2   | \$ 108.00              |           |                 |
| 10                           | RADIATOR GRILLE                             | 1   | \$ 1,754.00            | \$        | 1,403.20        |
| 11                           | FRONT BUMPER FOAM FILLER PIECE              | 1   | \$ 212.00              | \$        | 169.20          |
| 12                           | FRONT BUMPER REINFORCEMENT BEAM             | 1   | \$ 899.00              | \$        | 719.20          |
| 13                           | FRONT BUMPER BRACKET - RH                   | 1   | \$ 254.00              | \$        | 203.20          |
| 14                           | FRONT BUMPER GUIDE SECTION - LH / RH        | 2   | \$ 82.00               |           |                 |
| 15                           | FRONT BUMPER TOP COVER                      | 1   | \$ 143.00              | \$        | 114.00          |
| 16                           | CAUTION STICKER                             | 1   | \$ 16.00               | \$        | 12.40           |
| 17                           | AIR COND STICKER                            | 1   | \$ 9.00                | \$        | 6.64            |
| 18                           | FRONT BUMPER LOCK CARRIER BRACKET           | 1   | \$ 154.00              | \$        | 122.80          |
| 19                           | FRONT BUMPER SUPPORT - LH / RH              | 2   | \$ 64.00               | \$        | 51.04           |
| 20                           | POP RIVET                                   | 4   | \$ 4.00                | \$        | 2.88            |
| <b>SUB TOTAL SPARE PARTS</b> |                                             |     | <b>\$ 7,757.00</b>     | <b>\$</b> | <b>5,235.36</b> |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SBY 2222 H**

|                              |                                             |            | DAMAGED PARTS & PRICES |                    |
|------------------------------|---------------------------------------------|------------|------------------------|--------------------|
| S/N                          | PARTS DESCRIPTION                           | QTY        | S/NETT                 | REMARKS            |
|                              |                                             | <i>c/f</i> |                        | \$ <b>5,235.36</b> |
| 21                           | HORN - RH                                   | 1          | \$ 139.00              |                    |
| 22                           | HORN SUPPORT - RH                           | 1          | \$ 33.00               |                    |
| 23                           | FRONT PARKING AID SENSOR - INNER / OUTER    | 3          | \$ 488.00              |                    |
| 24                           | FRONT PARKING AID SENSOR SEAL RING          | 4          | \$ 10.00               |                    |
| 25                           | FROT BUMPER WIRING SET                      | 1          | \$ 642.00              |                    |
| 26                           | FRONT FENDER - LH / RH                      | 2          | \$ 2,454.00            |                    |
| 27                           | FRONT FENDER CLOSING ELEMENT - LH / RH      | 2          | \$ 162.00              |                    |
| 28                           | FRONT FENDER BRACKET - LH / RH              | 2          | \$ 82.00               |                    |
| 29                           | POP RIVET                                   | 12         | \$ 46.00               |                    |
| 30                           | FRONT FENDER BRACE - LH / RH                | 2          | \$ 264.00              |                    |
| 31                           | FRONT WHEEL HOUSING LINER - LH / RH         | 2          | \$ 518.00              |                    |
| 32                           | FRONT WHEEL HOUSING LINER ATTACHMENT PARTS  | 1          | \$ 149.00              |                    |
| 33                           | FRONT WHEEL SPOILER - LH / RH               | 2          | \$ 164.00              |                    |
| 34                           | FRONT WHEEL SPOILER LOWER - LH / RH         | 2          | \$ 79.00               |                    |
| 35                           | FRONT FENDER LEDGE COVER LONG - LH / RH     | 2          | \$ 70.00               |                    |
| 36                           | HEADLAMPS COVER - LH / RH                   | 2          | \$ 98.00               |                    |
| 37                           | BONNET                                      | 1          | \$ 3,425.00            | \$ <b>2,740.00</b> |
| 38                           | BONNET ATTACHMENT PARTS                     | 1          | \$ 431.00              |                    |
| 39                           | BONNET HINGE - LH / RH                      | 2          | \$ 680.00              |                    |
| 40                           | BONNET IMPACT PROTECTION - CENTER / LH / RH | 3          | \$ 93.00               | \$ <b>73.20</b>    |
| <b>SUB TOTAL SPARE PARTS</b> |                                             | :          | \$ <b>10,027.00</b>    | \$ <b>8,048.56</b> |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SBY 2222 H**

|                              |                                    |            | DAMAGED PARTS & PRICES |                     |
|------------------------------|------------------------------------|------------|------------------------|---------------------|
| S/N                          | PARTS DESCRIPTION                  | QTY        | S/NETT                 | REMARKS             |
|                              |                                    | <i>c/f</i> |                        | <b>\$ 8,048.56</b>  |
| 41                           | BONNET STRIKER - LH / RH           | 2 \$       | 112.00                 | <b>\$ 44.56</b>     |
| 42                           | BONNET LOCK                        | 2 \$       | 455.00                 |                     |
| 43                           | BONNET BOWDEN CABLE - CENTER       | 1 \$       | 64.00                  |                     |
| 44                           | BONNET RELEASE CABLE COVER         | 1 \$       | 11.00                  |                     |
| 45                           | BONNET RELEASE CABLE               | 1 \$       | 64.00                  | <b>\$ 50.56</b>     |
| 46                           | BONNET RELEASE LEVER               | 1 \$       | 15.00                  | <b>\$ 11.84</b>     |
| 47                           | PLENUM CHAMBER                     | 1 \$       | 108.00                 |                     |
| 48                           | HEADLIGHT - LH / RH                | 2 \$       | 16,344.00              | <b>\$ 6,537.60</b>  |
| 49                           | LIFT CYLINDER - LH / RH            | 2 \$       | 462.00                 |                     |
| 50                           | LIFT CYLINDER CORRUGATED PIPE      | 1 \$       | 107.00                 |                     |
| 51                           | LOCK CARRIER                       | 1 \$       | 1,127.00               |                     |
| 52                           | LOCK CARRIER SUPPORT - LH /RH      | 2 \$       | 85.00                  |                     |
| 53                           | CHARGED AIR COOLER                 | 1 \$       | 654.00                 | <b>\$ 522.80</b>    |
| 54                           | AIR COOLER PRESSURE HOSE - RH      | 1 \$       | 413.00                 |                     |
| 55                           | A/C CONDENSER                      | 1 \$       | 683.00                 | <b>\$ 546.00</b>    |
| 56                           | OUTSIDE TEMPERATURE SENSOR BRACKET | 1 \$       | 21.00                  | <b>\$ 16.32</b>     |
| 57                           | RADIATOR                           | 1 \$       | 1,010.00               |                     |
| 58                           | RADIATOR COOLANT                   | 6 \$       | 282.00                 | <b>\$ 37.60</b>     |
| 59                           | RADIATOR AIR GUIDE - LH / RH       | 2 \$       | 102.00                 | <b>\$ 40.08</b>     |
| 60                           | RADIATOR AIR GUIDE OUTER - LH / RH | 2 \$       | 38.00                  | <b>\$ 14.64</b>     |
| <b>SUB TOTAL SPARE PARTS</b> |                                    |            | <b>\$ 22,157.00</b>    | <b>\$ 15,870.56</b> |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SBY 2222 H**

|                             |                            |            | DAMAGED PARTS & PRICES |                     |
|-----------------------------|----------------------------|------------|------------------------|---------------------|
| S/N                         | PARTS DESCRIPTION          | QTY        | S/NETT                 | REMARKS             |
|                             |                            | <i>c/f</i> |                        | \$ <b>15,870.56</b> |
| 61                          | RADIATOR AIR GUIDE - UPPER | 1          | \$ 19.00               |                     |
| 62                          | RADIATOR AIR GUIDE - LOWER | 1          | \$ 25.00               |                     |
| 63                          | FRONT NO PLATE             | S/N        | \$ 60.00               | \$ <b>60.00</b>     |
| 64                          | SUNDRIES                   |            | \$ 350.00              | \$ <b>26.56</b>     |
| <b>TOTAL SPARE PARTS</b>    |                            | :          | \$ <b>40,395.00</b>    | \$ <b>15,957.12</b> |
| <b>TOTAL LABOUR CHARGES</b> |                            | :          | \$ <b>13,652.00</b>    | \$ <b>4,782.00</b>  |
| <b>GRAND TOTAL</b>          |                            | :          | \$ <b>54,047.00</b>    | \$ <b>20,739.12</b> |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

bl-25/02/22

## Supplementary Estimate-1

GST Reg No. 19-9902271-W

| AIG Asia Pacific Insurance Pte Ltd<br>78 Shenton Way<br>#07-16 AIG Building<br>Singapore 079120<br>Attn: Mr. Adrian Ling - Motor Claims Dept<br>Tel: 6841 0055 / Fax: 6256 4315 |                                                                                                             | Estimate No.<br>Date<br>Service Advisor<br>Pages<br>Regn No<br>Model No | PA/OD/0048/2022/JT<br>8-Feb-22<br>CHANG<br>1 of 1<br>SBY 2222 H<br>AUDI A4 2.0 TFSI |           |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-----------|
| Quantity                                                                                                                                                                        | Description                                                                                                 |                                                                         | Unit Price                                                                          | Amount    |
| <u>Labours</u>                                                                                                                                                                  |                                                                                                             |                                                                         |                                                                                     |           |
| 1                                                                                                                                                                               | TO DISLODGE AND REINSTALL FRONT LOCK CARRIER TO FACILITATE RENEWAL OF FRONT REINFORCEMENT BEAM BRACKET. S/N |                                                                         | \$ 780.00                                                                           | \$ 780.00 |
|                                                                                                                                                                                 | GRAND TOTAL                                                                                                 |                                                                         | \$ 780.00                                                                           | \$ 780.00 |

For Premium Automobiles Pte Ltd

---

Authorized Signature

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**NAME** :  
**SURVEYED DATE** :  
**AUTHORISED DATE** :  
**EXCESS COST** :  
**LIABILITY** :  
**REMARKS** :

**PLEASE NOTE** : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.  
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT